

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 31 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2557)

-----  
Set a post 3 ft. long, 3" sq., 2 ft. in the ground for ¼ sec. cor. marked ¼ S on N. face, from which  
A Fir 28" dia., bears N.23°W., 6 lks. dist. mkd. ¼ S BT.  
A Hemlock 6" dia., bears S.70½°W., 32 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
Jan. 1967 - C.S. File 54/12-18

-----  
Found - Orig. 28" now 32" Fir, shattered snag, N.23°W., 4.0 ft. shows "¼S" bark scribe on upper blaze in fair condition.  
SW. orig. BT could be under a pile of blow down.  
Set Brass cap at cor. mkd: County Surveyors Office  
¼ S 31 T 23 S R8W  
1967 T 24 S  
New BTs- 10" Hemlock N.65°W., 6.8 ft. mkd. ¼ S31 CS BT.  
6" Hemlock N.37°E., 15.0 ft. mkd. ¼ S31 CS BT.  
Corner lies 33.0 ft. East of ¼ cor. Sec. 6, T24S R8W.

Tony Hostetter - For: Weyerhaeuser - Jan. 2004 - C.S. File 65/49-13

-----  
Found - 1967 brass cap by Douglas Co. Surveyor as described by Tracy in 1967  
Both BTs marked Tracy in 1967 are present  
New BTs- 12" Fir, scribed "S31 ¼ BT" WEYCO tag, bears S.85°E., 45.9 ft. to spike placed in root collar below scribing.  
12" Fir, scribed "S31 ¼ BT" WEYCO tag, bears S.43°E., 30.4 ft. to spike placed in root collar below scribing.