

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 279100

PRIMARY CORNER DESCRIPTION Sec. Cor. 4 and 5 (North), T24-8 ONLY

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 6 Page(s) 2539)

Set a post 4½ ft. long, 4" sq., 24" n the ground for cor. to secs. 4 & 5 marked T24S S4 on SE and R8W S5 on SW faces with 4 notches on E and 2 notches on W edges, from which
A hemlock, 6" dia., bears S.61°E., 51 lks., mkd: T24S R8E S4 BT.
A hemlock, 8" dia., bears S.62°W., 26 lks., mkd: T24S R8E S5 BT.
A fir, 14" dia., bears N.5°W., 45 lks., mkd: T24S R8E BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Jan. 1967 - C.S. File 54/12-20A - **ADDED 11/29/2017**

Not Fd?
At the cor. of 4 & 5 we do not find any of BTs as called for, but find 24" Hemlock N.75°W., 49.8 ft. nearly turned out, we open & find "T & W" & fragmentary scribe on rotted face, under 60+ years of overgrowth now high stumped.

Tony Hostetter - For: Weyerhaeuser Co. - July 2003 - **ADDED 11/29/2017**- M142-67

Found 1/2" alum. pipe 75.5 ft west of brass cap [rec. 1.46 ch, 96.4 ft.] No evidence of orig. BTs. **Not accepted as corner for secs. 4 & 5.**