

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4, 5, 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

14" Fir with good scar, bears S.18°E., 15.4 ft.
10" Fir with good scar, bears N.64°E., 5.7 ft.
All other BTs mentioned in reference notes were taken out by road construction.
Using reference monument "B0 2", along with its backsight, I establish a position at record distance (per ref. notes of 229.48 ft.) Since "B0 1" no longer has a backsight, I can't check line from it, but do confirm rec. distance (per ref. notes of 62.4 ft.)
At this point, I SET a 1" x 30" I.P. with brass cap attached, stamped: "Douglas Co. Surveyor T23S S5 S4 S8 S9 R8W 1981". Since I hit bedrock down about 12", I build a large mound of dirt and stones approx. 18" high around the brass cap, which is no East shoulder of new road.
New BT - 10" Fir scribed "T23S R8W S8 CS BT" in double blaze bears S.34°W., 62.0 ft.

Fd. OK, Dec. 1995 by C. Mulkins - M 123-32

Ronald L. Rice, Ward NW - Aug. 8, 2008 - C.S. File 65/63-26

Found - 3" brass cap (properly mkd) dated 1981 with the following accessories:
44" D.Fir bears N.67°W., 25.1' - healed face
24" D.Fir bears S.13°E., 15.4' - healed face
15" D.Fir bears S.34°W., 62.0' - healed face
Record 15" D.Fir bearing N.64°E., 5.7' - down, out of position.
New BT - 19" D.Fir bears N.38°E., 26.9' - blazed, scribed "T23S R8W S4 BT"
Note - Corner has steel post adjacent to it. All BTs have red painted bands & yellow tags.
Compass decl. 17°E.

Found & used by BLM resurvey by Michael O. Jones, Cadastral Surveyor under special instructions dated May 27, 2009 - Surveyed June/July 2009 - (DCS0 records BLM plat 2011 & Vol. 56 Page 22267)
Latitude 43°35'29.48"N. Longitude 123°39'49.68"W.
(NAD 1983 (CORS 96))

Fd per rec. 8/2019 - C.S. File 65/102-73 by R. Quimby

FD OK DCS0 (SJF & JL) 7/22/2021 - C.S. File 67/51-13 - note: 19" D.Fir from 2008 report now high stump)