

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2570)

-----  
Set a post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on West face, from which  
A Fir 40" dia., bears S.3°E., 88 lks. dist. mkd. ¼ S BT  
A Maple 10" dia., bears N.1°W., 72 lks. dist. mkd. ¼ S BT

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
March 1967 - C.S. File 54/12-61

-----  
Found - Orig. 40" now 50" Fir, alive, S.3°E., 58.1 ft., previously opened and shows "4S" scribe and axe notch.

No trace of orig. NW. BT.

Set Brass cap at cor. mkd: County Surveyors Office  
T 23 S R 8 W  
¼ S 15 | S 14  
1967

New BTs- 20" D.Fir N.51°E., 7.6 ft. mkd. ¼ S14 CS BT.

16" D.Fir N.86°W., 26.8 ft. mkd. ¼ S15 CS BT.

Corner lies 40 ft. N. of top ridge, course E. and W. Best route to cor. is by jeep trail, if dry, on top of ridge, line tag on N. side of road.

Fd. OK, Aug. 1982 by R. Hintz - M 92-60