

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2561)

-----  
I destroy ¼ secs. cor., and at 40.72 chains, which is in middle of sec. line, I mark a leaning Laurel 16" dia., with (.) at exact point and ¼ S, from which  
A Fir 18" dia., bears N.16°W., 14 lks. dist. mkd. ¼ S BT.  
A Fir 20" dia., bears S.64°W., 50 lks. dist. mkd. ¼ S BT.  
(Note, I did not find any recorded information regarding a previous ¼ sec. cor. V. Laugen, March 1997)

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Feb/March 1967 - C.S. File 54/12-28

-----  
Found - No trace of corner tree.  
Orig. 18" now 30" Fir, alive, N.16°W., 9.2 ft., previously opened and face burned. No scribe found.  
Orig. 20" now 36" Fir, now stump, S.64°W., 33.0 ft., open and find "¼S" scribe and reverse.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 23 S R 8 W  
¼  $\frac{S \ 13}{S \ 24}$   
1967  
New BTs- 27" D.Fir N.30°E., 36.4 ft. mkd. ¼ S13 CS BT.  
12" D.Fir S.27°W., 77.3 ft. mkd. ¼ S24 CS BT.  
Corner lies 15 ft. West of top of spur, sloping South.

Fd. OK, Feb. 1981 by L. Roberts - M 86-64

Fd. and used in BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 722 - Surveyed Aug 1970/Sept. 1970 - (DCSO records Vol. 35 Page(s) 14486)

Fd. and used in BLM resurvey by John A. Farmer, Cadastral Surveyor, under Group #1336, Surveyed Aug/Oct. 1986 - (DCSO records Vol. 48 Page(s) 18282-83)