

PRIMARY CORNER DESCRIPTION East 1/4 Cor. Sec. 31, only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #279, dated March 5, 1878 - (DCSO records Vol. 6 Page(s) 2633)

-----  
Set a Maple post, 5 ft. long, 5" dia., 20" in ground for the 1/4 sec. corner between secs. 31 & 32, from which  
A Fir, 24" dia., bears S.5°E., 18 lks.  
A Fir, 24" dia., bears S.6°W., 31 lks.

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 6 Page(s) 2655)

-----  
A Maple post 5" sq. 30' high, badly decayed, marked and witnessed as described by the surveyor general.

Michael S. McDowell - For: Weyerhaeuser Co. - Feb. 21, 1977 - M63-23 & C.S. File 58/139

-----  
Set - 1 1/2" gal. I.P. with brass cap, from which  
48" fir stump BT bark scribed bears S.48°30'W., 53.6 ft  
36" Fir stump RP bears S.31°30'E., 37.1 ft.  
**NOTE:** This corner set in error, see letter dated 4/12/1978 in C.S. File 58/139

Henry R. Reppeto - For: Weyerhaeuser Co. - April 12, 1978 - C.S. File 58/139

-----  
Partial content of letter dated April 12, 1978 to Douglas Co. Surveyor from Weyerhaeuser: "We have destroyed all accessories to the corners we set (NE Cor. Sec. 31 and the NW Cor. Sec. 32) as well the East 1/4 Cor. of Sec. 31. Enclosed is a plat for the corrected position of the East 1/4 corner of sec. 31, based on the cadastral location of the NE corner and latest GLO record distances & bearings". See M 63-23 for orig. Weyerhaeuser map & C.S. 58/139 for replacement.  
Set - A 1 1/2" gal. I.P. with brass cap.  
No live trees of sufficient size available for BTs.  
Referenced the following partially rotted stumps with tags & gal. spikes but did not scribe:  
48" Fir stump S.18°E., 23.2 ft.  
48" Fir stump S.60°W., 56.6 ft.

Tony Hostetter - For: Weyerhaeuser Co. - March 2007 - C.S. 65/60-23

-----  
Found - 1 1/2" iron pipe and brass cap as Set by Weyerhaeuser in (C.S. 58/139)1978 continued next page

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 200139

PRIMARY CORNER DESCRIPTION East 1/4 Cor. Sec. 31, only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From which:  
48" fir stump, WEYCO tag & "W" nail, bears S.18°E.,  
23.2 ft to "W" nail  
48" fir stump, WEYCO tag & "W" nail, bears S.60°W.,  
56.6 ft to "W" nail.  
New BTs- 12" fir, WEYCO tag & spike, bears N.16°W., 25.0 ft  
to spike  
11" fir, WEYCO tag & spike, bears N.40°E., 9.3 ft to  
spike  
14" fir, WEYCO tag & spike, bears N.72°E., 15.2 ft  
to spike.