

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4; & 33 T22-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - William H. Byars, Deputy Surveyor, Under Contract No. 279 , dated March 5, 1878 - (DCSO records Vol. 4 Page(s) 1650)

Set a chitewood post 4 ft. 5" dia., 18" in ground, for the ¼ sec. corner from which

A fir, 40" dia., bears N.25°W., 63 lks.

A fir, 40" dia., bears South, 60 lks.

BLM resurvey by Joseph M Mannix & Edith M Forkner, Cadastral Surveyors Under group No. 2727 surveyed Oct. 2013/April 2014 - (DCSO records Vol. 58 Page(s) 23211)

Point for the ¼ sec. cor. of secs. 4 and 33, at proportionate dist.; there is no remaining evidence of the original cor. Set a stainless steel post, 28" long, 2½" dia., 20" in the ground, in a mound of stone, 2½ ft. base, to top, with a brass cap mkd.

T 22 S R 9 W

¼ $\frac{S\ 33}{S\ 4}$

T 23 S

2014

from which

A fir, 16" dia., bears N.12½°E., 21.6 ft., mkd. ¼ S33 BT.

A fir, 10" dia., bears S.36½°W., 38.9 ft., mkd. ¼ S4 BT.

Corner is located on the east edge of a creek, dry, 2 ft. wide, course N.60°W.

Each new bearing tree has a 2½"x1/4" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.

Each new corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post, unless otherwise noted in the corner description.

An aluminum angle iron, 5 ft. long, was driven alongside all corners unless an existing guard post was otherwise noted in the corner description.