

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor. Secs 27, 28, 33 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 6 Page(s) 2651-2)

I set a Hemlock post, 3 ft. long, 4" sq. 24" in ground for cor. of secs. 27, 28, 33, & 34, marked T23S S27 on NE; R9W S34 on SE; S33 on SW; and S28 on NW faces with 1 notch on S & 3 notches on E edges, from which,
A Fir, 30" dia., bears N.52½°E., 63 lks., mkd: T23S R9W S27 BT.
A Hemlock, 10" dia., bears S.82°E., 38 lks., mkd: T23S R9W S34 BT.
A Fir, 6" dia., bears S.88°W., 70 lks., mkd: T23S R9W S33 BT.
A Fir, 15" dia., bears N.34°W., 65 lks., mkd: T23S R9W S28 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - June 1970 - C.S. File 54/60-48

Found - Orig. 30" Fir N.52½°E., 41.6 ft., now only small part of shattered stump remains, no scribe found.
Orig. 10" now 28" Hemlock 12 ft. high snag, S.82°E., 25.1 ft., reverse scribe visible through hole on backside.
No trace other OBTs.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T23S R9W
OFFICE 1970 S 28 | S 27
S 33 | S 34
7" Hemlock S.20°W., 27.2 ft. mkd: T23S R9W S33 CS BT
20" Hemlock S.44°E. 45.0 ft. mkd: T23S R9W S34 CS BT
7" Hemlock N.76°W., 38.1 ft. mkd: T23S R9W S28 CS BT
7" D.Fir N.40°E., 21.4 ft., mkd: T23S R9W S27 CS BT

BLM dependent resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #927, surveyed Aug. thru Nov. 1977 - (DCSO records Vol. 41 Page(s) 16210)

Beginning at the cor. of secs. 27, 28, 33, & 34, perpetuated & recorded by Tracy in 1970, monumented with an iron post, 1" dia., firmly set, projecting 8" above ground with properly marked brass cap.
from which the remains of the orig. BTs
A decayed Fir stump, size indeterminate, bears N.52½°E., 63 lks., no marks visible.
A Hemlock snag, 28" dia., bears S.82°E., 38 lks., no marks visible.
continued next page

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor Secs 27, 28, 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and BTs mkd. by Tracy
A Fir, 10" dia., bears N.40°E., 33 lks., with healed blaze.
A Hemlock, 12" dia., bears N.76°W., 57½ lks with healed blaze.
No other suitable tress available within limits.

Tony Hostetter - For: Weyerhaeuser Co. - Dec. 2011 - C.S. File 65/76-7

Found - 1970 brass cap as described by Douglas Co. Surveyor (CS 54/60) Pipe is bent, ¾" Iron pipe alongside. 22" Fir DC BT, BT tag, bears N.40°E., 21.4 ft. to center.
20" Hemlock, DC BT, placed new WEYCO tag, bears N.76°W., 38.1 ft. to center.
New BTs- 20" Hemlock, scribed "S27 SW BT" WEYCO tag, bears N.65°12'E., 19.7 ft. to spike in root collar.
12" Fir, scribed "S28 SE BT" WEYCO tag, bears N.66°20'W., 7.5 ft. to spike in root collar.

BLM Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2756, surveyed May 2014 - (DCS0 records Vol. 58 Page(s) 23305-6)

The cor. of secs. 27, 28, 33, & 34, perpetuated by Hostetter, in 2011, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground (alongside of which is an iron pipe, 3/4" dia., firmly set, projecting 12" above ground), with a brass cap (properly) mkd. from which the remains of an original bearing tree
A decayed fir stump, size indeterminate, bears N.52½°E., 41.6 ft., no marks visible.
and the remains of the bearing trees mkd. by the Douglas County Surveyors Office in 1970
A root hole bears N.40°E., 21.8 ft., alongside of which is a down fir, 22" dia., with a healed blaze
A hemlock, 24" dia., bears N.76°W., 38.0 ft., with a healed blaze.
and the remains of the bearing trees mkd. by Hostetter
A hemlock, 21" dia., bears N.60¼°E., 21.7 ft., with scribe marks S27 SW BT visible on partially healed blaze and a nail at the base on the front center.
A root hole bears N.63½°W., 9.8 ft., alongside of which is a down fir, 11" dia., with scribe marks SE BT and other illegible scribe marks visible on partially healed blaze and a nail at the base on the front center.
continued next page

TOWNSHIP 23 RANGE 09 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor. Secs. 27, 28, 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

There are no new bearing trees available within limits in secs. 33 and 34. Drive an aluminum angle iron alongside the cor., which is located on the N. edge of a recently logged area, edge bears E. and W.
NAD 1983 (2011)
Latitude: 43°31'52.34" N Longitude: 123°46'01.51" W