

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Oscar F. Thiel, under contract # 688, dated June 9, 1898 - (DCSO records Vol. 7 Page(s) 2672)

-----  
At a point 100 ft. above stream, set a Hemlock post, 3 ft. long, 3" sq. 24" in the ground for ¼ sec. cor. mkd: ¼ S23 on N face and 26 on S face, from which:  
A Fir, 30" dia., bears N.38°W., 17 lks., mkd: ¼ S23 BT.  
A Fir, 6" dia., bears S.5°E., 36 lks., mkd: ¼ S26 BT.

Ronald Stuntzner - For: International Paper Co. - June 7, 1976 - M 60-41

-----  
Found - Metal fence post set by BLM  
Set - 5/8" iron rod alongside post, from which  
Orig. D.Fir, 44" now dead with face partially chopped out, N.38°E., 17 lks., (rec. N.38°W.)  
Orig. D.Fir, face partially chopped out, S.5°E., 23.8 ft. (36 lks.)  
New BT - 37" D.Fir, N.16°W., 16.2 ft.

Douglas County Surveyors Office - Randall Smith & Stephen Flause - 10/3/95 - C.S. 64/64-1

-----  
Found - 5/8" I.R. with yellow plastic cap mkd. "PE 6245" bent, protrudes 17" above ground.  
Bent fence post protrudes 30" above ground. Has a BLM tag attached date 1973.  
6" now 35" D.Fir, with a previously opened blaze, scribing visible "4", bears S.5°E., 23.8'.  
30" now 28" dia. 4' high broken & rotted D.Fir stump, bears N.38°E., 13.1' to center.  
37" now 37" dia. 5' high D.Fir stump, with a partially healed single blaze, scribing visible "¼", bears N.16°W., 16.2'.  
Set - Position of fence post and 5/8" I.R. is referenced & a 2 3/8" Dia. Brass cap on 1 3/8" O.D. by 32" long iron pipe is set at referenced position. BC/IP protrudes 10" above ground.  
Fence post if reset along north edge of BC/IP protrudes 36" above ground. (5' long)  
5/8" I.R. is set along south edge of BC I.P., protrudes 10" above ground (3' long).  
Cor. is surrounded by 1½' dia. mound of sand stone.  
4" dia. D.Fir, double blazed and scribe "X BT", bears S.67°W., 15.9'.  
11" dia. Hemlock, double blazed and scribed "¼ S23 CS BT", bears N.89°E., 54.6'.

cont.

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias	Description

BLM Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2756, surveyed May 2014 - (DCSO records Vol. 58 Page(s) 23304)

-----  
The ¼ sec. cor. of secs. 23 & 26, perpetuated by Stuntzner, in 1976; further perpetuated by Smith, in 1995; monumented with an iron post, 1 3/8" dia., firmly set, projecting 4" above a mound of stone, 2 ft. base, 8" high, with a brass cap (properly) mkd.

from which the remains of the original bearing trees

A decayed fir high stump, 28" dia., bears N.38°E., 13.1 ft., with axe marks visible on open blaze. (Record, N.38°W., 11.2 ft.)

A fir snag, 38" dia., bears S.5°E., 23.8 ft. with no marks visible on partially healed blaze at breast height. and the remains of a bearing tree mkd. by Stuntzner

A high fir stump, 30" dia., bears N.15°W., 16.0 ft., with the remains of a healed blaze.

and the bearing trees mkd. by Smith

A hemlock, 17" dia., bears N.89¾°E., 55.3 ft., with a healed blaze.

A fir, 15" dia., bears S.67½°W., 15.8 ft., with a healed double blaze.

Alongside the cor. is an iron rod, 5/8" dia., firmly set, projecting 4" above the mound of stone, with weathered plastic cap mkd. E 45, and a steel fence post with a BLM location tag.