

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 30; & 25, T24-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 7 Page(s) 2947)

Set ¼ sec. post below falls in creek 7 lks. wide, course NE.
Falls 20 ft. high almost perpendicular from which
A Cedar 9" dia., bears N.45°E., 47 lks. dist.
A Hemlock 5" dia., bears N.45°W., 52 lks. dist.

Douglas County Surveyors Office - J.W. Byron - March 1968 -
C.S. File 54/27-151

Looked for, not found.
Logging debris at log landing. No trace of BTs. NE.
possibly buried under debris.