

PRIMARY CORNER DESCRIPTION NW Corner Tract 40 (Sec. 36)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page(s) 13289)

Point for the NW cor. of Tract No. 40, sec. 36
Set an iron post, 28" long, 2½" dia., 24" in the ground, and in a small mound of stone, with brass cap mkd.

T 24 S R 2 W
S 35 | S 36
TR 39 | TR 40
1963

from which

- A fir, 32" dia., bears N.61¼°E., 53 lks., mkd: S36 BT.
- A fir, 30" dia., bears S.21½°E., 36 lks., mkd: TR40 S36 BT

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - Dec. 9, 1986 - C.S. File 62/38-3

Found - 1963 GLO 2½" dia., by 28" long IP with brass cap out of ground leaning against NE BT. (Cap properly marked)

32" now 33" dia., 5 ft. high D.Fir stump with a fully healed single blaze that we partially open & find scribing "BT" bears N.61¾°E., 35.0 ft. (agrees with rec.)

30" now 31" dia., D.Fir with a fully healed single blaze bears S.23½°E., 23.8 ft. (Rec. S.21½°E., 23.8 ft.)

Set - Brass cap/IP set at position determined by intersecting distance & bearings (SE BTs bearing slightly different than rec.) Old flagging was fd. approx. 1 ft. under ground in hole dug to reset BC/IP. We stamp 1963 BLM cap "RESET 1986". BC/IP protrudes 10" above ground, surrounded by a 2½ ft. dia., mound of stone.

The NE cor. TR 39, a 2½" dia., I. pipe & brass cap bears N.21½°E., 64.7 ft.

New BTs- 9" Maple double blazed & scribed "S36 CS BT" bears N.81½°E., 23.0 ft.

20" D.Fir double blazed & scribed "TR 39 CS BT" bears S.55°W., 14.0 ft.

Corner lies at SW corner of new clearcut on steep NW slope.