

PRIMARY CORNER DESCRIPTION Sec. Cor. for 24 & 25 only (East)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 7 Page(s) 2874) and duplicate Pg. 2762)

-
- Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 19, 24, 25 and 30 marked T24S S19 on NE.; R1W S30 on SE.; R2W S25 on SW.; and S24 on NW. faces, with 4 notches on N. and 2 notches on S. edges, from which
- A Fir 16" dia., bears N.10°E., 30 lks. dist. mkd. T24S R1W S19 BT.
 - A Maple 5" dia., bears S.31°E., 13 lks. dist. mkd. T24S R1W S30 BT.
 - A Fir 60" dia., bears S.49°W., 42 lks. dist. mkd. T24S R2W S25 BT.
 - A Hemlock 12" dia., bears N.60°W., 20 lks. dist. mkd. T24S R2W S24 BT.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 7 Page(s) 2940)

-
- I find post badly decayed and accessory trees not agreeing with data furnished by the Surveyor General. This line being incorrect in alignment and position, I re-establish cor. at the same point as follows:
- Set a Maple post 4 ft. long, 4" sq., 24" in the ground for cor. of secs. 24 and 25, marked T24S S25 on SW. and R2W S24 on NW. faces, with 2 notches on S. and 4 notches on N. edges, from which
- A Fir 60" dia., bears S.59°W., 33 lks. dist. mkd. T24S R2W S25 BT.
 - A Hemlock 12" dia., bears N.49°W., 19 lks. dist. mkd. T24S R2W S24 BT.

Survey by Bruce Shaner - For: Evans Products Co. - April/May 1965 - M 29-65

-
- Set Square post from which a:
- 60" D.Fir, Orig. BT, with old face, but bark scribes, now missing, I newly scribed "T24S R2W S25 BT", bears S.59°W., 22.0 ft.
 - 16" D.Fir, Orig. BT, set by McQwinn in 1883 with bark scribes visible, bears N.21°E., 24.2 ft. (Chapman & Nicklin in 1896, said this tree did not fit- - -)
 - 12" Hemlock BT, set by C & N, now missing.
 - 38" D.Fir, I scribed "T24S R2W S24 BT", N.8°W., 37.7 ft.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 24 & 25 only (East)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM Resurvey by Lynn M. Roseberry, Cadastral Surveyor - Under Group #634 Surveyed, May 1967 - (DCSO records Vol. 34 Page(s) 14171)

Point for the cor. of secs. 24 and 25 only, restored by the method of irregular boundaries at proportionate position; there is no remaining evidence of the original corner.

Set an iron post, 6" long, 1" dia., 5" into a crevice of a rock outcropping, with brass cap mkd.

T 24 S	T 24 S
S 24	R 1 W
S 25	S 19
R 2 W	
	1967

from which

A point of a rock outcropping, bears S.60°W., 10 lks. dist., mkd. with a cross.

A Fir 36" dia., bears N.51°W., 97 lks. dist. mkd. T24S R2W S24 BT.

Corner falls on a rock outcropping facing E.

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1051, surveyed April 1981/Aug. 1982 - (DCSO records Vol. 45 Page(s) 17333)

The Cor. of secs. 24 and 25 only, T24S R2W, monumented with an iron post, 1" dia., firmly set, projecting 1" above rock outcrop, with brass cap as mkd. in 1967, from which a bearing object and the remains of a bearing tree mkd. by Roseberry:

A rock outcrop bears S.60°W., 10 lks. dist. with fragmentary chisel marks visible on E. face.

A root hole bears N.51°W., 97 lks. dist., with down Fir alongside, 38" dia., with fragmentary scribe marks visible on decayed blaze.

and a new bearing object

A rock outcrop bears N.25°W., 19 lks. dist. mkd. X BT.