

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 31 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

The ¼ sec. cor. of sec. 31 only, monumented with an iron post
1" dia., 10" above ground, firmly set, with brass cap mkd.

¼ S 31
1944

from which original bearing tree:

A Fir 22" dia., bears S.40°E., 56 lks. dist, with a
partially healed blaze, the scribe marks having been
destroyed in 1944, by Price.

and a bearing tree by Price in 1944:

A Cedar turnout 10" dia., bears N.39°E., 20 lks.
dist., with scribe marks ¼ S visible on partially healed
blaze.

and bearing tree by County in 1955:

A Fir 24" dia., bears N.84½°W., 85 lks. dist. mkd. ¼ S31
T24S R3W BT.

and a new bearing tree:

A Fir 7" dia., bears N.65½°E., 41 lks. dist. mkd. ¼ S31
BT.

Fd. OK, Sept. 1966, V.R. Tracy, DCSO C.S. File 54/27-77

Greg Lang - For: Seneca Jones Timber Co. - April 2001 -
M 138-6 & C.S. File 65/37-5F

Found - 1944 BLM brass cap properly mkd.
14" D.Fir bears N.65 ¾°E., 26.9 ft. Glenn. Set
spike in the base of the tree & placed new tag.
26" D.Fir bears S.43°E., 37.1 ft. Byars. Set spike
in the base of the tree & placed new tag.
30" D.Fir bears N.85½°W., 56.1 ft. Byron. Set spike
in the base of the tree & placed new tag.

New BTs- 14½" D.Fir bears S.2½°W., 7.7 ft. scribed "¼ S31
only" "BT" Set spike in the base of the tree &
placed new tag.

Set Alum. post at corner.

Note - On ridge at fence corner.