

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 3004)

-----

Set chittim post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. marked ¼ sec. cor. mkd. ¼ S on N face from which  
A dogwood, 8" dia., bears N.10°E., 39 lks., mkd: ¼ S BT.  
A cedar, 12" dia., bears S.52°W., 76 lks., mkd: ¼ S BT.

BLM dependent resurvey by Norman D. Price, Cad. Engineer, under Group 242 surveyed June/Aug. 1950 (DCSO recs. Vol. 27 Page(s) 11479)

-----

Point for the ¼ sec. cor. of secs. 4 & 9, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼  $\frac{S\ 4}{S\ 9}$   
1950

from which  
A fir, 26" dia., bears N.41°45'E., 27 lks., mkd: ¼ S4 BT.  
A hemlock, 18" dia., bears S.29½°W., 77 lks., mkd: ¼ S9 BT

Weyerhaeuser Co., Albert Potter - May 1964 - C.S. 53/111-15

-----

Found - 1950 Brass cap in good condition.  
26" Fir stump faced & scribed, rec. N.41°45'W., 17.8 ft., N.41°E., 13.1 ft.  
18" Hemlock, W.29½°W., 50.8 ft. - GONE.

New BT- 58" Fir stump, S.51°E., 33.0 ft., with "W" nail & plate.  
Add "W" nail & plate to 26" fir stump.  
Mag. decl. 20°

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Sept. 1967 - C.S. File 54/27-87

-----

Found - 1950 GLO brass cap, buried.  
26" Fir, now stump, N.41¾°E., 14.3 ft., moved by logging should be 17.9 ft., scribe visible.  
18" Hemlock, now stump, S.29½°W., 50.8 ft., scribe showing. This BT under logging debris.

Set - 6 ft. steel fence post alongside brass cap.

New BT - 58" Fir stump S.53°E., 33.1 ft. mkd: ¼ S9 CS BT.

Note - Also Weyerhaeuser "W" nail at base of new BT.  
This corner lies on steep SW slope 70 ft. E of Creek. 3 ft. wide, course S in clear cut unit.

Cont.

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Robert Cook - For: Weyerhaeuser Co. - 12/2010 - M161-57  
-----

Found - 1950 GLO brass cop on 3/4" pipe flush with ground on  
SW slope about 70 ft NE of a creek. I set 6'  
steel post east 0.5'. BTs found:

58" D.Fir stump S.53°E., 33.1 ft with tag.

26" D.Fir stump N.41°30'E., 17.9 ft with tag.

New - 17" D.Fir N.27°W., 8.3 ft scribed " ¼S4" above "BT".

18" D.Fir S.80°E., 18.3 ft scribed " ¼S9" above "BT".

RR spike control points lie N.25°31'47"E 724.61' and  
N.7°47'23"E., 1080.72'.