

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 400320

PRIMARY CORNER DESCRIPTION S 1/16 Secs 21 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Marion Hale, WEYCO - March 1955 - C.S. File 51/31-1 ----- Set stake for corner by single proportionate method. Referenced by Marion Hale (plates and "W" nails only) Declination 20° 46" Fir stmp N.54°E., 29.7' 28" Fir stmp N.13½°E., 2.2'</p>
<p>Glen McChesney, WEYCO - April 1964 - C.S. File 51/31-5 ----- Set 1" aluminum pipe for corner by single proportionate method. Conforms to location determined by L.E.Calder & H.A.Gould in 1942 Referenced by Glen Mcchesney (Weyerhaeuser method with disc #2149) Declination 20° 22" R. Cedar N.41°E., 17.9' 48" Fir Stp. N.40°W., 29.8'</p>
<p>Dan Baker, For: Weyerhaeuser Co. - Dec. 8, 1983 - M90-48 ----- Set - 1½"x40" iron pipe with brass cap 19" hemlock, S.78°E., 31.8' 36" fir stump, N.21°W., 22.8' Note- 1" al. pipe set by WEYER. CO. bears S.83°39'08"E., 10.69'</p>
<p>Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 8/29/2024 - C.S. File 67/58-60 ----- Found - 2½" brass cap up 3" 25" Hemlock S.80°E., 33.7 ft. (rec S.78°E., 31.8 ft to face) fully healed single blaze, add 3½" mag nail right side center. Very rotted 30"x6 ft. stump N.23°W., 24.3 ft. (rec. N.21°W., 22.8 to face.) Face fallen off, scribes S1/16 S21 BT. Steel T post N.3°E., approx. 2 ft. New - 5/8"x30" iron rod with DCSO plastic cap N.40°E., 26.3 ft. set in East road shoulder up 3". Note - Area burnt 9/2020 Compass decl. 14¼°E. Mon in old forest regrowth on moderate east slope approx 10 ft. west of center of N-S gravel road. Oregon Coordinate Reference System Cottage Grove - Canyonville Zone N 229974.004 E 238915.032</p>