

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2953)

-----  
Set ¼ sec. post from which  
A fir, 40" dia., bears N.50°W., 15 lks.  
A fir, 30" dia., bears S.32°W., 23 lks.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Sept. 1967- C.S. File 54/27-84

-----  
Found - Stumps of orig. BTs as fd. by Forest app., 1952.  
Orig. 40", now 43" Fir stump N.50°W., 9.9 ft., bark gone, no scribe, forest app. tag mkd. to be on NW BT.

Orig. 30", now 33" Fir stump, S.32°W., 15.2 ft. bark gone, no scribe fd. (face measure)

Find old blazes west of corner.

Set - Brass cap at cor. mkd: County Surveyors T24S R3W  
(set steel fence post Office ¼ S 10  
6' long, 2' E of cor.) 1967 S 15

New BTs- 22" Maple N.81°E., 111.4 ft. mkd: "¼ S10 CS BT"  
(Note: BT is live stub)

6" D. Fir S.58½°E., 114.4 ft. mkd: ¼ S15 CS BT"

Note - This corner lies in logged-off area on gentle southerly slope.

Dan Baker, For: Weyerhaeuser Co. - Dec. 8, 1983 - M90-48

-----  
Found - 1¼" iron pipe with Douglas Co. brass cap "1967"  
36" fir stump, N.45°W., 12.7 ft. (ctr. meas.) orig. BT. No marks.

33" Fir stump, S.28°W., 15.8 ft. (ctr. meas.) Orig. BT no marks.

28" Maple, N.85°E., 111.5 ft. (ctr. meas.) Doug. Co. BT. Scribe visible.

New BTs- 14" Fir, N.32½°E., 9.4 ft.

13" Fir, S.18°E., 5.6 ft.