

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Secs 2, 3, 10, & 11

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2951)

Set post cor. to secs. 2, 3, 10, & 11 from which
A maple, 8" dia., bears N.85°E., 22 lks.
A maple, 6" dia., bears S.20°E., 25 lks.
A maple, 8" dia., bears S.32°W., 11 lks.
A maple, 8" dia., bears N.5°W., 29 lks.

Fd. & used on GLO survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 2983)

Weyerhaeuser Co. - April 19, 1963 - C.S. File 53/111-3

All orig. BTs gone.
W. Co. 1958 (C.S. 53/111-16) -
54" Fir N.68°E., 13.9 ft. now stump, added a plate.
60" Fir N.13°W., 14.1 ft. now stump 1958 error dist. should be 15.1 changed plate to 15.1.
27" Fir S.17°E., 38.6 ft. now stump.
48" Fir S.17°W., 49.7 ft., now a windfall.
Set - 1"x30" alum. pipe, 1963 - 1"x6' marker pipe.
BT - 54" Fir stump N.68°E., 13.9 ft. "W" nail plate.

Fd. Ok by DCSO V.R. Tracey Oct. 1967 C.S. 54/16-26A