

PRIMARY CORNER DESCRIPTION SW Cor. Langley Hall DLC #38

Alias	Description

<p>DLC Survey by - Dennis Hathorn, under contract dated Sept 1856 (DCSO DLC records Pg 147)</p> <p>-----</p> <p>Marked an Oak, 36" dia., for cor. - from which An Oak, 36" dia., bears N.45°E., 148 lks. An Oak, 36" dia., bears N.55°W., 34 lks.</p>	
<p>Douglas Co. Surveyors Office -Douglas Co. Surveyors Office - James Byron, Dep. Co. Surveyor - Sept. 28, 1956 - C.S. File 47/141</p> <p>-----</p> <p>Found - Orig. BTs open & find scribing, check for bearing and distances. Position of corner determined from Orig. BTs.</p> <p>Set - An iron pipe with brass cap at corner point mkd: SW DLC 38 T24S R4W, COUNTY SURVEYORS OFFICE 1956 9" W.Oak, bears N.16°E., 22.0'. 9" W.Oak, bears N.80°E., 33.9', scribed SW Cor DLC 38 CS BT</p>	
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Jan. 10, 2014 - C.S. File 67/41-11</p> <p>-----</p> <p>Found - A 2½" dia., brass cap (properly mkd) on a 1" I.D. iron pipe set protruding 8" above ground. Evidence of the 2 orig. BTs: Two large, deep and irregular root-holes are fd at the rec. bearings and distances. The orig. oak, 36" dia., in the NW quadrant is now a fallen and rotted 55" dia. B.Oak with a previously opened blaze showing reheal burling but with all blaze and scribing evidence rotted away. A 9" W.Oak now a 13" dia., W.Oak with a fully healed double blaze; bears N.14½°E., 22.0 ft. (Rec. N.16°E., 22.0') 1956 A 9" W.Oak now an 11" dia., W.Oak with a fully healed double blaze; bears N.78½°E., 33.9 ft. (Rec. N.80°E., 33.9') 1956</p> <p>New - A 13" dia., I.Cedar scribed "SW DLC 38 CS" "BT" on a double blaze; bears S.56¾°W., 42.7 ft. A 28" dia., D.Fir scribed "SW DLC 38 CS" "BT" on a double blaze; bears N.54¾°W., 42.1 ft.</p> <p>Note - Monument is on flat bench in a gentle north slope and in an older fir and oak forest. Compass decl. 15½°E.</p>	
<p>1</p>	