

Alias	Description

DLC Survey by - Dennis Hathorn, under contract dated Sept 1856 (DCSO DLC records Pg 156)

Set a post for cor. - from which
An Oak, 24" dia., bears S.14°W., 308 lks.
An Oak, 15" dia., bears N.89½°E., 447 lks.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - May 1963 - C.S. File 53/9-73

Found - 44" W.Oak, S.14°W., 203.3', opened & fd. reverse scribing on overgrowth of old face "4W", tree hollow, face had apparently rotted badly before growing over.
27" W.Oak, N.89½°E., 295.0', no scar visible.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1963
T24S R4W SW COR DLC 45 |
7" D.Fir, S.2°W., 73.0', mkd: SW DLC 45 CS BT.
(?) D.Fir, N.38°E., 109.0', mkd: SW DLC 45 CS BT.
(Dia. of tree not in orig. notes)

Corner lies in open pasture land approx. 600' south of Driver Valley Road.

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Dec. 3, 2013 - C.S. File 67/41-2

Found - 2½" dia., brass cap (properly mkd) on a 1" I.D. x32" iron pipe. The monument is bent and tipped 2.3 ft. south from its plumb position.
Accessories are measured from fd. monument's plumb position.

An oak, 24" dia., now a large distinct root-hole with some oak fragments; bears S.14°W., 203.3 ft. (As per rec.) OBT

An Oak, 15" dia., now a 21" dia., rotted fallen and out of position oak with a previously opened blaze (no scribing fd); the distinct root-hole of which bears N.89½°E., 295.0 ft. (as per rec.) OBT

A 7" D.Fir, now a 30" dia., D.Fir with a fully healed double blaze; bears S.3½°W., 72.2 ft. (rec. S.2°W., 73.0') 1963

A (?) D.Fir now a 47" dia., D.Fir with a fully healed double blaze; bears N.39½°E., 109.0 ft. (rec. N.38°E., 109.0' 1963

New - Determined plumb position of fd. BC monument agrees well with fd OBT evidence and reasonably well with fd. renewal BTs. continued next page

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 045030

PRIMARY CORNER DESCRIPTION SW Cor. Elizabeth Johnson DLC #45

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

The plumb monument position is referenced out and the BC/IP is removed from ground.
The BC/IP is straighten and is reset plumb at the referenced out position and now protrudes 1" above ground.
A 14" dia., W.Oak scribed "SW DLC 45 CS" "BT"; bears N.88°E., 152.9 ft.
A 10" dia., D.Fir scribed "SW DLC 45 CS" "BT"; bears S.23½°E., 40.2 ft.
Sketch in file shows a fence running NE-SW north 60'
Note - Monument is near edge of small field on a gentle NW slope with fir & oak forest to North, South and East with open pasture to the NW.
Compass decl. 15½°E.