

PRIMARY CORNER DESCRIPTION Int SE Wm Allen DLC #47

Alias	Description

<p>DLC Survey by - Dennis Hathorn, under contract dated Sept 1856 (DCSO DLC records Pg 158)</p> <p>-----</p> <p>Set post for cor. - from which An Oak, 18" dia., bears S.59°W., 394 lks. An Oak, 15" dia., bears S.53°W., 250 lks.</p>
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - March/April 1963 - C.S. File 53/9-47</p> <p>-----</p> <p>Found - 32" B.Oak, S.59°W., 260.0', cut open & find good scribing "BT". Did not find other BTs.</p> <p>Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1963 T24S R4W INT. L DLC 47 --- 9" W.Oak, S.52½°W., 155.7', mkd: Int L DLC 47 CS BT 14" W.Oak, N.44½°W., 150.7' mkd: Int L DLC 47 CS BT Corner lies on bare west slope in pastured area.</p>
<p>Fd. ok by Templin - 6/1996 - M 125-36</p>
<p>Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - 2/11/2015 (Filed 1/27/2021) - C.S. File 67/48-2</p> <p>-----</p> <p>Found - 1¼" Iron Pipe (I.D.) by Godfrey in 1963 per C.S. File 53/9-47, firmly set, projecting 12" above the ground with a 2½" brass cap (properly) mkd. An original BT - A down and rotted B.Oak, size indeterminate, bears S.59°W., 260.0 ft. with no marks visible And BTs by Godfrey in 1963 per C.S. 53/9-47 - A 13" W.Oak bears S.52½°W., 155.7 ft. with a healed double blaze A 25" W.Oak bears N.44½°W., 150.7 ft. with a healed double blaze</p> <p>New - A 7" I.Cedar bears N.2½°E., 131.9 ft. scribed "X BT" Note - Compass declination 15½°E. All BTs have BT tags attached. All new BTs have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown. Corner falls approximately 35 ft west of a N-S wire fence line on a brushy west slope.</p>