

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>Original - Gordon &amp; Gardner, Contract #52 dated Feb. 1855 (DCSO records, Volume 7 Page 3026)</p> <p>-----</p> <p>Set ¼ sec. post, from which A B.Oak 12" dia. bears N.11½°W., 351 lks. dist. A B.Oak 12" dia. bears S.69°W., 532 lks. dist.</p>
<p>Milo E. Godfrey, Deputy Co. Surveyor - V. Tracy; M.Stone May-June 1963 - C.S. File 53/9-119</p> <p>-----</p> <p>Found - Mound of rock at corner. (No record) (2/11/1918 Frear notes: "Germond ¼ cor. S.S." in Field Book 43 Pg. 55) (Info. added 10/91, V.L.&amp; date added 5/12/2011 JC) Old Oak, down &amp; partly rotted, N.11½°W., 231.7 ft. opened &amp; found fragmentary but legible reverse scribing "¼S". 30" B.Oak S.69°W., 351.1 ft. alive &amp; standing, shows good scars, did not open. Set brass cap at cor. mkd: County Surveyors T24S R4W ¼ <u>S31</u> Office, 1963 T25S R4W S 6 Replace rocks around cap. New Bts- 15" W.Oak N.10½°W., 148.5 ft. mkd: ¼ S31 CS BT. 9" W.Oak S.28°E., 59.6 ft. mkd: ¼ S 6 C S BT. Corner lies 8 feet west of a North &amp; South fence line.</p>
<p>Fd. OK, July 1976 by W. Barnes - M 60-70</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 1/10/2002 - C.S. File 66/32-4</p> <p>-----</p> <p>Found - 1963 DCSO Brass Cap/iron pipe protrudes 12" above ground, mound of stone around base of BC/IP. Corner lies 8 ft. West of a N-S fence line. 12" B.Oak now badly rotted remains, found at rec. N.11½°W., 231.7 ft. (OBT) 12" now 34" dia., down &amp; rotting B.Oak fd. at rec. S.69°W., 351.1 ft. (OBT) 15" now 24" dia., W.Oak with a fully healed double blaze bears N.10½°W., 148.5 ft. (1963) 9" now double trunked W.Oak with a fully healed double blaze on 16" dia., Westerly trunk, bears S.28°E., 59.6 ft. (1963) New - 7" dia., D.Fir double blazed &amp; scribed "¼ S6 CS BT" bears S.37½°W., 89.5 ft. 6" dia., D.Fir double blazed &amp; scribed "¼ S6 CS BT" bears S.67½°E., 80.9 ft. - Compass decl. 17½°E.</p>