

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Gordon & Gardner, Contract #52 dated Feb. 1855  
(DCSO records Vol. 7 Page(s) 3035)

-----  
Set ¼ sec. post from which  
A W.Oak, 6" dia., bears N.70°E., 12 lks.  
A Fir, 12" dia., bears N.10°W., 67 lks.

BLM dependent resurvey by Charles E. Akin, Jr., Cadastral  
Surveyor, Group # 793, surveyed Aug. 1972 (DCSO records Vol.  
36 Page(s) 14855-56)

-----  
Point for the ¼ sec. cor. of secs. 34 & 35, at proportionate  
distance; there is no remaining evidence of the orig. corner.  
Set an iron post, 28" long, 2½" dia., 22" in the ground, with  
brass cap mkd: T 24 S R 4 W

¼  
S 34 | S 35  
1972

from which  
A Fir, 27" dia., bears S.59°E., 71½ lks., mkd: ¼ S35 BT.  
A Fir, 6" dia. bears N.85°W., 42½ lks., mkd: ¼ S34 BT.

BLM dependent resurvey by Lance J. Bishop & James L. White,  
Cadastral Surveyors, Group #1233, Surveyed Oct. 1984/Jan.  
1985 (DCSO records Vol. 47 Page(s) 18021)

-----  
Point for the ¼ sec. cor. of secs. 34 & 35, at proportionate  
distance; there is no remaining evidence of the orig. corner.

From this point, the ¼ sec. cor. erroneously reestablished by  
Akin, in 1972, bears S.5°18'E., 0.51 chs.

Remove the iron post, destroy the marks on the trees and at  
the true corner point

Reset the iron post, 28" long, 2½" dia., 24" in the ground,  
with brass cap mkd: T 24 S R 4 W

¼  
S 34 | S 35  
1985  
1972

from which  
An Ash, 15" dia., bears N.61°E., 65½ lks., mkd: ¼ S35 BT.  
A Fir, 29' dia., bears N.76°W., 51 lks., mkd: ¼ S34 BT.

(Cont. next page)

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found & used by BLM dependent resurvey by Wayne L. Rogers & Boyd W. Peterson, Cadastral Surveyors, under Group #1314, surveyed April/May 1986 (DCSO records Vol. 48 Page(s) 18273)

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - Sept. 20, 1993 - C.S. File 64/47-5

-----  
Found - 3 1/4" BLM BC on a 2 1/2" IP, protrudes 3" above ground.  
32" now 32" dia., 2' high D.Fir stump w/partially  
healed lower blaze, no scribing vis. bears  
N.76°W., 33.7', agrees w/rec. 1985 BLM  
14" now 15" dia., ash w/partially healed single  
blaze scribing vis. "1/4 S35 BT" bears N.61°E.,  
43.2', agrees w/rec. 1985 BLM  
New BOs- 5" D.Fir double blazed & scribed "1/4 S35 CS BT" bears  
S.38°E., 42.2'.  
7" "X" chiseled in top of NW corner of concrete  
cattle guard structure, bears S.5°E., 66.2' .  
13" dia., Maple, double blazed and scribed "1/4 S.34  
CS BT" bears N.53 1/4°W., 100.5'.

Corner lies approx. 60' northerly of a gravel road and cattle  
guard, 8' West of a north-south running fence line.

Fd. OK by H. Christensen, 12/1995 - M 123-21