

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855  
(DCSO records Vol. 7 Page(s) 3031)  
-----  
Set ¼ sec. post from which  
    A Fir, 36" dia., bears S.60°W., 18 lks.  
    A Fir, 10" dia., bears N.25°W., 11 lks.

GLO dependent resurvey by Lynn M. Roseberry, Cadastral  
Surveyor, Group #349, surveyed Aug/Sept 1957 (DCSO records  
Vol. 28 Page(s) 12104)  
-----  
Point for ¼ cor. at proportionate distances, there is no  
remaining evidence of the orig. corner.  
Set an iron post, 30" long, 2" dia., 24" in the ground, with  
brass cap mkd:     T24S R4W  
                     $\frac{1}{4} \frac{S}{S} \frac{2}{11}$   
                    1957  
from which  
    A Fir, 21" dia., bears N.6½°W., 72 lks., mkd: ¼ S2 BT.  
    A Fir, 24" dia., bears S.40½°W., 90 lks., mkd: ¼ S11 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy -  
Vernon Tracy; Mike Stone, crew - June 1963 - C.S. File 53/9-  
111  
-----  
GLO brass cap in good condition, both BTs mkd in 1957 alive  
and in good condition.