

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855
(DCSO records, Volume 7 Page 3034)

Set ¼ sec. post from which
 A W.Oak, 10" dia., bears s.58°W., 57 lks.
 A Pine, 15" dia., bears N.20°W., 12 lks.

Douglas Co. Surveyors Office - C.E. Roberts, Co. Surveyor -
May 1903 - F.B. No. 7 Pg. 14

Reset post, made new BT
 Fir, 48" dia., N.67°E., 22 lks.

Searched for, not found, Milo Godfrey DCSO - 6/10/1963 C.S.
File 53/9-99 - Fence corner only at approx. location.

BLM Resurvey by C. Albert White & Norman J. McDonald,
Cadastral Surveyors, under Group #'s 243, 350, & 513,
surveyed April/July 1963 - (DCSO records Vol. 32 Page(s)
13463)

Point for the ¼ sec. cor. of secs. 25 & 36, at proportional
distance; there is no remaining evidence of the original
corner.
Set an iron post, 28" long, 2½" dia., 24" in the ground
with brass cap mkd: ¼ $\frac{S}{S}$ $\frac{25}{36}$
from which
 A Cedar, 18" dia., bears N.20°W., 21 lks., mkd: ¼ S25 BT.
 A Fir, 8" dia., bears S.36°W., 42 lks., mkd: ¼ S36 BT.

FD. ok by Kris DeGroot, 8/2008 - 2008-0061A-G