

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 12

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Oscar F. Theil, Contract #658, May 1896 (DCSO records Vol. 7 Page(s) 3063)

A fir, 20" dia., for ¼ sec. cor. which I mkd. ¼ S on N side, from which
 A Cedar, 5" dia., bears S.45°W., 24 lks., mkd: ¼ S BT.
 A Fir, 9" dia., bears N.51°E., 36 lks., mkd: ¼ S BT

GLO dependent resurvey by Lynn M. Roseberry, Cadastral Surveyor, Group #349, surveyed Aug/Sept 1957 (DCSO records Vol. 28 Page(s) 12101)

The ¼ cor. monumented by a Fir, 27" dia., marked with a healed blaze on the N. side, from which the orig. BTs:
 A Fir, 16" dia., bears N.25°E., 36 lks., mkd: ¼ S BT on opened blaze. (Rec. bearing N.51°E.)
 A Cedar, 6" dia., bears S.42°W., 24 lks., mkd: ¼ S on partly rotted blaze. (Rec. bearing, S.45°W.)
and a new bearing tree,
 A Fir, 19" dia., bears S.9½°W., 30 lks., mkd: ¼ S12 BT.

Les Roberts - For: Seneca Jones Timber Co. - Oct. 1999 - M133-54

Found - 28" corner tree with healed blaze on north side.
 6" Cedar, S.42°W., 15.8' (scribe vis.) 1896 BT
 16" Fir, N.25°E., 23.8' (scribe vis.) 1896 BT
 22" Fir, S.10°W., 20.0' (scar vis.) 1957 BT
Set - 5/8" x 30" iron rod with yellow plastic cap for witness corner. Iron rod bears N.89°02'W., 5.00' from center of 28" corner tree.