

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31, T23S R3W

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by James P. Currin, Deputy Surveyor, under Contract #438, dated May 2, 1882 - (DCSO records Vol. 6 Page(s) 2298) (and Pg. 2211)

-----  
Set a sandstone 12x8x6 ins., 8" in the ground for cor. to Tps. 23 & 24 S., Rs., 3 & 4 W, marked with 6 notches on each edge, from which  
A Cedar 36" dia., bears N.1°E., 75 lks. dist. mkd. T23S R3W S31 BT.  
A Cedar 30" dia., bears S.30°E., 100 lks. dist. mkd. T24S R3W S6 BT.  
A Hemlock 14" dia., bears S.60°W., 37 lks. dist. mkd. T24S R4W S1 BT.  
A Fir 46" dia., bears N.30°W., 90 lks. dist. mkd. T23S R4W S36 BT.

Above Cor. used in GLO survey by Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 2969)

Tied into corner in GLO survey by Oscar F. Thiel, Deputy Surveyor, under Contract #658 dated May 21, 1896 (DCSO records Vol. 7 Page(s) 3078-79)

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 6 Page(s) 2320)

-----  
Found corner which is a sandstone 12x8x6 ins. in mound of stone, marked and witnessed as described by the surveyor general. This cor. I reestablish as follows: Set a sandstone, 12x8x6 ins. in mound of stone for SW. cor. of T23S R3W., marked with 6 notches on N. and E. edges; from which  
A Cedar 36" dia., bears N.1°E., 75 lks. dist. mkd. T23S R3W S31 BT.  
Excavation impracticable. I destroy all other accessories to this corner.

BLM resurvey by Norman D. Price, Cadastral Engineer, under Group #242, surveyed June/Aug. 1950 - (DCSO records Vol. 27 Page(s) 11457-58)

-----  
The SW. cor. of T23S R3W is monumented with a sandstone, 12x8x6 ins., firmly set, mkd. with 6 grooves on N. face; from which the remains of the original bearing trees:  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31, T23S R3W

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Fir stub 22" dia., bears S.57°45'W., 37 lks. dist. with partial scribe marks on charred face of old blaze. Record, a Hemlock bearing S.60°W., 37 lks. dist.  
A Fir stub 50" dia., bears N.30°W., 90 lks. dist. with partial scribe marks on charred bark blaze.

At the corner point

Set an iron post, 3 ft. long, 3" dia., 28" in the ground, and in a circular mound of stone, 4 ft. base, to top, with the original stone deposited at the base, with brass cap mkd:

T 23 S  
R 3 W  
S 31  
-----  
T 24 S R 4 W  
S 1  
1950

from which

A Fir 30" dia., bears N.21°E., 266 lks. dist. mkd. T23S R3W S31 BT.

A Fir 60" dia., bears N.63°45'E., 257 lks. dist. mkd. T23S R3W S31 BT.

Bruce Malcom - Weyerhaeuser Co. - Jan. 17, 1962 - C.S. File 53/107-10

-----  
Found - 1950 Iron post and cap present, also original stone.  
Orig. 30" Fir, N.21°E., 266 lks., now a stump, scribing visible.  
Orig. 60" Fir, N.63°45'E., 257 lks., now a stump, scribing visible.

Accessories Added this date:

30" Fir stump, N.21°E., 175.6 ft. "W" nail & plate.  
60" Fir stump, N.64°E., 169.6 ft. "W" nail & plate.  
24" Fir S.59°W., 54.2 ft. "W" nail and plate.  
5" chinquapin S.43°E., 8.5 ft. "W" nail and plate.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; M. Stone - July 1963 - C.S. File 53/9-114

-----  
Found - Brass cap set by Price in mound of rocks.  
30" Fir stump, sawed high, N.21°E., 175.6 ft., all scribing visible.  
82" Fir stump N.63 3/4°E., 169.6 ft., scribing visible "31 BT".  
Two Fir snags mentioned by Price:  
22" Fir stub S.57 3/4°W., 24.4 ft. charred face.  
50" Fir snag N.30°W., 59.4 ft. axe scar on bark, charred.

(Cont. Next Page)

TOWNSHIP 24 RANGE 04 POINT IDENTIFIER # 678676

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31, T23S R3W

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs- 28" D.Fir S.59°W., 55.1 ft. mkd. T23S R3W S31 CSBT.  
7" Chinq. N.54°E., 35.8 ft. mkd. T23S R3W S31 CS BT.  
No more suitable trees available to NE.