

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Robert Elder, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3101)

-----  
Set post cor. to secs. 10, 11, 14 and 15, from which  
A Y.Oak 20" dia., bears S.47°E., 96 lks.  
A Y.Oak 20" dia., bears S.74°W., 189 lks.  
A Y.Oak 24" dia., bears N.50°E., 352 lks.  
No other tree near.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - March 1960 - C.S. File 49/124-26

-----  
Found - I open orig. 20", now dead, 40" B.Oak, S.74°W., 124.7 ft. and find good scribing.  
Orig. SE BT alive, shows good scars. I do not open.  
Orig. NE BT, center rotted, previously opened.  
All check record bearing and distance.  
Corner 20.4 ft. North of fence.  
Set Brass cap at cor. mkd:

County Surveyors Office  
T 24 S R 5 W  
S 10 | S 11  
S 15 | S 14  
1960

New BTs -18" R.Fir bears S.29°E., 18.9 ft. scribed S14 T24S R5W CS BT.  
12" Laurel bears S.17°W., 19.7 ft. scribed S15 T24S R5W CS BT.  
6" R.Fir bears N.45°W., 22.9 ft. scribed S10 CS BT.  
17" R.Fir bears N.79°E., 39.9 ft. scribed S11 T24S R5W CS BT.

Douglas Co. Surveyors Office - R.B. Kimberling, Deputy - P.L. Earle, crew - March 13, 1978 - C.S. File 59/46-77

-----  
Found - A 1" x 36" I.P. set 22" in ground, bent over, with a 1960 county brass cap, properly marked.  
20" now 60" B.Oak (Rec. Y.Oak) bears S.44°E., (Rec. S.47°E.) 63.4 ft. with well healed scars.  
20" now 36" Oak is down, on blaze area, approx. bears S.74°W., 124.7 ft.  
24" now 32" burned out Oak snag, bears N.51½°E., (Rec. N.50°E.) 232.3 ft. with reverse scribing "4" in a healed blaze.  
18" now 24" D.Fir (R.Fir) bears S.29°E., 18.9 ft. with a well healed double blaze.  
12" now 13" Madrone (Laurel) measured below the fork, bears S.17°W. 19.7 ft with well healed double blaze.  
(Cont. Next Page)

TOWNSHIP 24 RANGE 05 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

6" now 11" D.Fir (R.Fir) bears N.45°W., 22.9 ft.  
with a well healed double blaze.  
17" now 23" D.Fir (R.Fir) bears N.79°E., 39.9 ft.  
with a well healed double blaze.  
I straighten the bent iron pipe and reset in original  
location, stamp "RESET 1978" above existing date "1960".  
Brass cap is 3" above ground.  
Corner is on North edge of a Jeep trail, 20.0 ft. North of an  
E-W fence.

Fd. OK, April 1992, D.Bentz, Land Partition 1992-0031  
Fd. OK Dec. 2004 by C. Sweeden - land partition 2004-0083  
Fd. Ok 10/2007 by K. DeGroot - 2007-0146A&B