



TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 100640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & 1 of T24-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM Resurvey by Dale Bedell - May 1992 thru April 1993 under group # 1637. (DCSO records Vol. 51 Pg. 19541)

-----  
Point for the 1/4 sec. cor. of secs. 1 and 6, at proportionate distance, there is no remaining evidence of the original corner.

Set - A stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

T24S  
R7W R6W  
1/4  
S 1 | S 6  
1993

from which bearing trees mkd. by Brooks -

A Fir, 15" dia., bears S.58°E., 111 lks. dist., with healed blaze.

A Fir, 21" dia., bears S.30 3/4°W., 70 lks dist., with healed blaze.

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

NOTE - From this point, the ¼ sec. cor. of secs. 1 and 6 erroneously reestablished by Brooks in 1964 bears S.67°04'00"E., 0.530 chs. dist., monumented with an iron post, 2½" dia., firmly set, projecting 2" above the ground, with brass cap marked marked and witnessed as described in the official record. Amend the brass cap to read "T24S R7W R6W ¼ S1 S6 1957 AMENDED 1993" and reset monument flush with the ground.

Mark Smalley - for: Roseburg Forest Products - Dec. 6, 1996 - C.S. 65/15-6D

-----  
Mon. Fd.- 1993 Cad. I.P.B.C.  
Bt's Fd.- 16" Fir, S.58°E., 73.3' good healed face  
21" Fir, S.30°W., 46.3' good healed face - does not face corner

New Accessories -  
13" Cedar, N.62°W., 16.4' scribed "¼ S BT"  
13" Cedar, S.82°E., 21.4' scribed "¼ S BT"

continued next page

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 100640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & 1 of T24-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

David Edwards, For: Dory Construction - 2/2019 - M175-23  
-----

Found - BLM brass cap  
14" dia., 6 ft tall fir stump with healed blaze  
bears S.58°E., 73.3'  
25" fir with healed blaze bears S.30¼°W., 46.2'  
13" cedar with 1996 RFP tag & healed blaze bears  
S.82°E., 21.4'  
14" cedar with 1996 RFP tag & healed blaze bears  
N.62°W., 16.4'