

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3153)

-----  
Set ¼ sec. post, from which  
A Fir 24" dia., bears S.46°E., 44 lks. dist.  
A Fir 18" dia., bears S.52½°W., 96 lks. dist.

F.C. Frear; J. Wolford; P.D. Wolford and B. Lane - Nov. 22, 1932 (no record source, see "old" corner book, page 48)

-----  
Reset from 2 old BTs. One down. I set a 1" x 36" I.Pipe, from which  
A 24" Fir bears N.22¼°W., 61.6 ft.  
A 4" Laurel bears N.54½°W., 67.0 ft.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, W. Penley, crew - Sept. 3, 1970 - C.S. File 52/102-10

-----  
Found - 1" I.P., 36" long, in old N-S fence line and scribed stake, "¼S"  
4" now 10" Laurel N.54½°W., 67.0 ft., has old axe face, rotten.  
24" Fir, now rotted stump, N.22°W., 47.0 ft. (Rec. 61.6 ft.) found no scribing.

Set Brass cap at cor. mkd: County Surveyors Office  
T 24 S R 6 W  
¼ S29 | S28  
1970

New BTs -14" D.Fir N.26°W., 21.5 ft. scribed ¼ S29 CS BT.  
16" D.Fir N.47°E., 21.9 ft. scribed ¼ S28 CS BT.

Douglas Co. Surveyors Office - Stephen J. Flause, Deputy - Karen Mosley; Terri Plouff, crew - Feb. 23, 1981 - C.S. File 61/19-8

-----  
Found - 1970 DCSO brass cap on a 1" I.P., protruding 10" from ground, firmly set, properly marked.  
A 1" I.P. protruding 7" from ground, firmly set, on the South edge of brass cap/I.P. monument.  
The monuments are in an old N-S fence are are approx. 5 ft. North of a fence corner with fences running N. and S. & W.  
A search is made for orig. BTs but only possible evidence of SW BT is found; at rec. bearing and dist. (S.52½°W., 63.4 ft.) is a tipped over 26" dia., Fir, the NE face of which is not accessible for investigation and no evidence of blazing is found on the rest of its trunk. (Cont. Next Page)

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A 24" Fir is not found at record brg. & dist., however a rotted Fir stump from 1970 is found at N.22°W., 43.0 ft. (Rec. N.22°W., 47.0 ft.) Tree has no evidence of blazing or scribing.  
A 4" Laurel now a 12" DBH Madrone bears N.54½°W., 67.0 ft. Tree has opened blaze, no scribing visible. 1932 BT.  
A 14" D.Fir now an 18" DBH D.Fir bears N.26°W., 21.5 ft. Tree has a healed double blaze, no scribing visible. 1970 BT.  
A 16" D.Fir now a 20" DBH D.Fir bears N.47°E., 21.9 ft. Tree has a healed double blaze with no scribing visible.  
Monument position is accepted.  
New BT - A 12" DBH D.Fir bears S.75½°E., 39.1 ft. Tree is scribed ¼ S CS BT on a double blaze.  
DCSO bearing tree tags are placed on the Madrone (Laurel) and on the new bearing tree.

Les Roberts - For: Guistina Resources Inc. - March 2000 - M134-38

-----

Found - 1970 Douglas Co. iron pipe & brass cap.  
12" Madrone, N.54°W., 67.0' (scar vis), 1932  
26" Fir stump, N.26°W., 21.5' (scar vis), 1970  
28" Fir, N.47°E., 21.9' (scar vis) 1970  
14" Fir S.75°E., 39.1' (scar vis) 1981

Set - 12" B.Oak S.36°W. 26.3' (scribed/metal washer/painted red)