

TOWNSHIP 24 RANGE 06 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors,
under Contract #31 dated April 7, 1853 (DCSO records Vol. 8
Page(s) 3147)

Set ¼ sec. post, from which
A W.Oak 14" dia., bears N.50°E., 58 lks. dist.
A W.oak 20" dia., bears S.6°W., 176 lks. dist.

Not Fd. by DCSO 2/11/1971 (added 3/28/2017) C.S. File 52/102-
17: Area logged & badly burnt. Had good line from 27, 28, 33,
& 34 which is (OK). Also good call 2.50 chains from top of
ridge.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, under
Group #969, surveyed April/May 1979 (DCSO records Vol. 42
Page(s) 16487)

Point for the ¼ sec. cor., at proportionate distance; there
is no remaining evidence of the original corner.
Set an iron post 28" long, 2½" dia., 24" in the ground with
brass cap mkd:
T 24 S R 6 W
1/4 $\frac{S\ 27}{S\ 34}$
1979

from which
A Fir 4" dia., bears N.73¼°E., 22½ lks. dist. mkd. X BT.
A Fir 5" dia., bears S.8½°E., 24 lks. dist. mkd. ¼ S34 BT
Corner is located 25 lks. South of woven wire fence,
extending E. and W.

Fd. Ok by D. Edwards, 10/2005 - M148-79