

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 8 Page(s) 3145)

Set post cor. to secs. 10, 11, 14 and 15, from which

- A Laurel 18" dia., bears N.11½°E., 29 lks. dist.
- A Laurel 15" dia., bears S.72°E., 60 lks. dist.
- A Laurel 20" dia., bears S.19°W., 81 lks. dist.
- A Fir 14" dia., bears N.80°W., 71 lks. dist.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, V. Perron, crew - Aug. 12, 1970 - C.S. File 52/102-32

Found - Old fence corner post that has been used for sec. cor. for at least the last 60 years. There are no orig. BTs left, but at the locations where they should be, we find slight depressions in ground. We re-run F.Frear's road tie from end of Co. Rd. #73, done in 1925, and again come out to fence corner. To determine end of Co. Rd., we use old Cherry tree tied to by Frear which bears S.32°E., 48.5 ft. Since old fence corner post is set very solid and in good condition, we set brass cap 6" E. of old fence corner.

Set Brass cap at cor. mkd: County Surveyors Office

T 24	S R 6	W
<hr/>		
S 10	S 11	
S 15	S 14	
1970		

New BTs -10" W.Oak N.63°E., 40.3 ft. mkd. T24S R6W S11 CS BT
 9" D.Fir S.8°E., 35.4 ft. mkd. T24S R6W S14 CS BT.
 10" D.Fir S.54°W., 5.2 ft. mkd. T24S R6W S15 CS BT
 10" D.Fir N.37°W., 20.8 ft. mkd. T24S R6W S10 CS BT

This corner lies on westerly slope 100 ft. E. of roadway and 161.0 ft. E. of creek (Rec. 191.4 ft.) The channel of creek has been changed about 30 ft. to E. by old logging road in bottom of ravine according to Mr. Sparks, landowner, who has lived in same place for 61 years and says that the fence corner as described above has been used as the section corner as long as he can remember.

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, and Glenn Baughman, LS #536 under Group #'s 826 and 856, Surveyed Sept. 1973/Aug. 1975 (DCSO records Vol. 37 Page(s) 15240-41)

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias	Description
Alias	Description
Alias	Description
Alias	Description

The Sec. cor., perpetuated and recorded by Tracy in 1970, monumented with an iron post, 2" dia., firmly set in a mound of stone, 5 ft. base, to top, with a 1970 DCSO brass cap. from which the remains of the original bearing trees:

- A root hole bears N.11½°E., 29 lks. dist.
- A root hole bears S.72°E., 60 lks. dist.
- A root hole bears S.19°W., 81 lks. dist.
- A root hole bears N.80°W., 71 lks. dist.

and the remains of bearing trees mkd. by Tracy:

- A W.Oak 12" dia., bears N.63°E., 59 lks. dist., with fragmentary scribe marks visible on partially healed blaze.
- A Fir snag 9" dia., bears S.10°E., 53½ lks. dist., with scribe marks T24S R6W S14 CS BT visible on open blaze.
- A Fir 12" dia., bears S.54°W., 7½ lks. dist., with fragmentary scribe marks visible on partially open blaze.
- A Fir 12" dia., bears N.37°W., 31½ lks. dist., with fragmentary scribe marks visible on partially healed blaze.

and a new bearing tree:

- A Fir 7" dia., bears S.70½°E., 89 lks. dist., mkd. T24S R6W S14 BT.

BLM Resurvey by Wayne L. Rogers, Cadastral Surveyor, under Group #1623, surveyed Sept/Oct. 1991 (DCSO records Vol. 50 Page(s) 19227)

The Sec. cor., monumented with an iron post, 1¼" dia., firmly set, projecting 18" above ground, with 1970 County brass cap. from which bearing trees mkd. by Tracy in 1970

- A White Oak 16" dia., bears N.63°E., 59 lks. dist. with healed blaze.
- A Fir 22" dia., bears S.54°W., 7½ lks. dist. with healed blaze.
- A Fir 18" dia., bears N.37°W., 33½ lks. dist. with healed blaze.

and a bearing tree by Berry, Akin, and Baughman

- A Fir 15" dia., bears S.70½°E., 89 lks. dist. with healed blaze.

and the remains of a tree of which I have no record

- A sawed and burned Fir stump 26" dia., bears S.86°E., 51½ lks. dist. with healed blaze.

Fd. Brass cap, Sept. 1995 by D. Bentz - C.S. File 63/165-4
Fd. OK by C. Sweeden, Sept. 2002 - 2002-0038 A & B
FD. BC, 3 BTs, NE BT stump, by C. Sweeden, 2/2012 - M163-27