

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec Cor for 30 & 31; 25 & 36, T24-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3194-95)

Set post cor. secs. 30, 31, 25 and 36, from which
A Fir 20" dia., bears N.85°W., 200 lks. dist.
A Fir 20" dia., bears S.75°E., 127 lks. dist.
A Fir 30" dia., bears N.15°E., 135 lks. dist.
An Oak 15" dia., bears S.1°W., 508 lks. dist.

Fd. and tied in GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3315)

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - Sept. 1960 - C.S. File 49/41-35

Found - Orig. 30" now 60" R.Fir N.15°E., 89.1 ft., shows good scar below and small section of bark blaze above.
Orig. 20" now 60" R.Fir N.85°W., 132.0 ft., shows good old bark scribing "S0".
Orig. 20" now 48" R.Fir S.75°E., 83.8 ft., old face rotted.

This corner renewed by County Surveyor in 1956, brass cap set and BTs scribed but not recorded. We move Brass cap 2.5 ft. N.85°W., to true position as determined by orig. BTs.
New BTs and BTs scribed in 1956:

17" R.Fir S.8°W., 58.4 ft. scribed S36 T24S R8W CS BT.

18" forked Laurel S.17½°E., 10.7 ft. scribed S31 T24S R7W CS BT.

Rescribed (bark) orig. now 48" R.Fir S.75°E., 83.8 ft. "T24S R7W CS BT S31".

Fd. OK May 1987 by H. Johnstone - M 104-16

M.Smalley for Roseburg Forest Prod. Jan. 1999 - M131-12

Found 1956 County brass cap on iron pipe.
BT's - 58" Fir, N.15°E., 89.1 ft. healed, original
35" Madrone, S.17½°E., 10.7 ft. healed
31" Fir, S.8°W., 58.4 ft. healed
69" Fir, N.85°W., 132.0 ft. healed, original
48" Fir, N.28°W., 11.0 ft. BLM tag, no face (no previous record)

continued next page

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec Cor for 30 & 31; 25 & 36, T24-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor, under Group No. 2102, surveyed May 2005 - Jan. 2006 - (DCSO records Vol. 56 Page(s) 22311 & Plat T24-8 2011)

The cor. of secs 25, 30, 31, & 36, on the E. bdy. of the Tp., remonumented by the DCSO in 1956 and 1960, monumented with an iron post, 1¼" dia., firmly set projecting 12" above ground, with brass cap (properly) mkd.

- from which the remaining orig. BTs
 - A fir, 59" dia., bears N.15°E., 89.1 ft. with a healed blaze.
 - A burnt, decayed fir snag, size indeterminate, bears S.75°E., 83.8 ft. with no marks visible.
 - A fir, 73" dia., bears N.85°W., 128.4 ft. with a healed blaze and marks DN visible in the bark. (Rec. 132.0 ft) and BTs mkd. by the DCSO in 1960
 - A double trunk madrone, 37" dia., S.17°E., 10.6 ft. with a healed double blaze.
 - A fir, 37" dia., S.8¼°W., 58.2 ft. with a healed double blaze.
- and BT mkd. by person(s) unknown
 - A fir, 50" dia., bears N.13¾°W., 10.9 ft. with mark X visible in the bark.