

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

16" now 16" dia., Oak with a fully healed single blaze, bears N.63½°W., 110.3 ft. (agrees w/rec.)
No other BTs found.
A 38" dia. D.Fir with faint blaze was previously opened by Jim Artman, PLS #2268. We opened further, no blazes or scribing found inside tree. Tree bears S.83½°W., 178.8 ft. from 5/8" Iron rod.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - March 30, 1996 - C.S. File 64/66-15

Found - 5/8" I.R. protrudes 5" above ground.
33" dia. D.Fir with a fully healed single blaze, bears S.81°W., 50.4 ft.
16" dia. Oak, now down, root hole agrees with record brg. and dist. N.63½°W., 110.3 ft.
Iron rod falls directly below an E-W fence.
No new monument set.
New BTs- 10" dia. Alder, bark scribed "¼ S29 CS BT", bears N.84°E., 407.9 ft. to root crown.
6" dia. D.Fir, double blazed and scribed "¼ S29 CS BT", bears N.6½°W., 117.7 ft.
14" dia. W.Oak, double blazed and scribed "¼ S29 CS BT", bears N.65 3/4°W., 131.0 ft.

Found OK by C. Sweeden, Aug. 2001 - 2001-0103 A&B
Found OK by D. Edwards, Dec. 2002 - M141-29

DCSO-GIS Corner visitation - 4/18/2005 - Typed: 1/24/2011 - C.S. File 67/33-1

Monument - 5/8" I.R. rebar.
Comment - OK