

PRIMARY CORNER DESCRIPTION CN 1/16 Secs. 5

Alias	Description

BLM Resurvey by C. Albert White, Cadastral Surveyor and Donald R. Beck, Surveying Technician, Under Group #515, Surveyed June/Oct. 1963 - (DCSO records Vol. 32 Page(s) 13487)

-----  
Point for the Center N 1/16 sec. cor. of secs. 5.  
Set an iron post, 28" long, 2½" dia., 21" in the ground, with brass cap marked:

C  
N 1/16 S 5  
1963

from which

- A fir, 12" dia. bears N.81½°E., 61 lks. mkd: CN 1/16 S5 BT
- A cedar, 25" dia. bears N.40°W., 53 lks mkd: CN 1/16 S5 BT

Douglas Co. Surveyors Office - Stephen J Flause - Mike Koch - 8/29/2014 - C.S. File 67/41-58

-----  
Found - The orig. 1963 monument, a 3¼" dia., brass cap (properly mkd) on a 2" I.D. iron pipe leaning approx. N.60°E., 0.25 ft. and protruding 7" above ground.

OBTs - Accessories are measured from the plumb position of the above fd. monument.

A fir, 12" dia., now a large shallow root-hole near the record bearing and distance.

A cedar, 25" dia., now a red cedar, 44" dia., with a fully healed blaze; bears N.40°W., 35.0 ft. (as per rec.)

New - BC monument is returned to its plumb position and now protrudes 6" above ground.

A D.Fir, 20" dia., scribed "CN 1/16 S5 CS" "BT" on a double blaze; bears N.66½°E., 20.0 lks.

Note - Monument is on flat pasture land with scattered maple, alder, fir, cedar and yew.

Compass decl. 15½°E.