

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 33 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3206)

Set ¼ sec. post, from which
A Fir 6" dia., bears S.2°W., 26 lks. dist.
A Fir 9" dia., bears S.45°E., 48 lks. dist.

Survey by Bruce Shaner Engineering - For: U.S. Bureau of Land Management - Dec. 11, 1972 - M 49-7

Found - Orig. 32" D.Fir, face previously opened, scribing visible, bears S.2°W., 17.2 ft.
Orig. 28" D.Fir bears S.35°E., 31.7 ft., (Rec. S.45°E.)
Set a brass cap mkd. T24S R7W WM S33 S34 ¼S 1972.

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, under Group # 807 Surveyed June/July. 1973 (DCSO records Vol. 37 Page(s) 15295)

The ¼ sec. cor. of secs. 33 and 34, perpetuated and recorded by Shaner in 1972, monumented with an iron post 28" long, 1½" dia., firmly set, protruding 8" above ground with brass cap mkd. in 1972
from which the remaining bearing tree
A Fir 33" dia., bears S.2°W., 26 lks. with fragmentary scribe marks visible on opened blaze.
and a new bearing tree
A Fir 11" dia., bears S.62½°E., 81½ lks. mkd. ¼ S34 BT.

Fd. and used in BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #998, surveyed Oct/Nov. 1979 - (DCSO records Vol. 43 Page(s) 16656-57)

Mark Smalley - For: Roseburg Resources - May 2003 - M142-29

Found - 1972 BLM brass cap on an iron pipe.
39" Fir S.2°W., 17.2' healed (Orig.)
13" Fir S.62½°E., 53.8' healed
New BTs- 10" W.Fir N.19°W., 23.6' "¼S BT"
22" W.Fir N.44°E., 31.8' "¼S BT"