

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 8 Page(s) 3271 and Page 3275-76)

(Page 3271)

Marked a Fir 4" dia., for ¼ sec. cor. marked ¼ S on N. side, from which

A Fir 50" dia., bears S.43°W., 18 lks. dist. mkd. ¼ S BT

A Fir 40" dia., bears N.51°E., 31 lks. dist. mkd. ¼ S BT

(Page 3275-76)

I destroy the ¼ sec. cor. and at 37.35 chs., which is in middle of the line, I set post 4" sq., 4 ft. long, 24" in the ground for ¼ sec. cor. marked ¼ S on N., from which

A Laurel 12" dia., bears S.27°W., 25 lks. dist. mkd. ¼ S BT.

A Fir 8" dia., bears N.87°W., 20 lks. dist. mkd. ¼ S BT.

I destroy the NE. cor. on left bank of Umpqua River.

Gene E. Johnson, R.E. 3561 - May 1956 - C.S. File 42/151

Corner reset using erroneous corner to 15 and 22 (supposedly destroyed) which was set in 1893.

Found - 54" Fir stump S.43°W., 18 lks. chopped out BT scribing.

48" Fir stump N.51°E., 31 lks. with old face rotted out.

Corner was reset 2.65 chs. East of old corner. (See orig. notes) At 2.54 chs. East, I found Madrone stump bearing S.27°W., 25 lks. (OBT) and stump hole of Fir, bears N.87°W., 20 lks. (OBT)

At corner point, I SET a 3/8" x 30" Iron bolt, from which 40" Fir bears N.40°15'E., 58.7 ft. mkd. ¼ S15 RE 3561 BT
No other trees available.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Debbie Stewart, crew - Aug. 6, 1981 - C.S. File 61/27-63

Found - 3/4" x 30" bolt (rec. 3/8" x 30"), firmly set, protruding 8" out of ground.

46" Fir, orig. 40", bears N.40°E., 58.7 ft., bark scribed "¼ S15 RE 3561 BT". This tree to be cut down.

No trace of either original BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 7 W

¼ S 15

1981

(Cont. Next Page)

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

I replace found 3/4" bolt along the northerly edge of B.C.
New BTs- 42" Fir stump 4 ft. tall bears N.18°E., 8.5 ft. to
set boat spike in top.
8" Fir bears N.31°W., 26.2 ft. scribed ¼ S15 CS BT,
double blaze.
7" Fir bears N.75°E., 18.9 ft. scribed ¼ S15 CS BT,
double blaze.
7" Chinquapin bears S.5°W., 13.8 ft. scribed ¼ S22
CS BT in double blaze.
All trees have DCSO BT tags.

Fd. Ok by C. Sweeden, Aug. 1997 - M 124-61
Fd. OK, Feb. 2001 by C. Sweeden - M136-63
Fd. Ok by C. Sweeden, 8/2005 - 2005-0084 A&B