

TOWNSHIP 24 RANGE 07 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 8 Page(s) 3197)

Marked a Fir 15" dia. for ¼ sec. post, from which
A Fir 6" dia., bears S.80°W., 5 lks. dist.
A Fir 12" dia., bears N.85°E., 12 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Clete Putnam, crew - July 12, 1961 - C.S. File 49/41-46

Found - Original corner tree, now down.
Orig. NE. BT, we open and find good scribing "4".
This BT now down.

Set brass cap at corner and in E-W fence line, mkd:
"¼ S14|S13 T24S R7W County Surveyors Office 1961"
(This brass cap set in concrete under E-W fence, 1962)
New BTs- 5" R.Fir bears S.75°W., 61.7 ft. scribed ¼ S14 CS BT
20" R.Fir bears N.60°E. 34.8 ft. scribed ¼ S13 CS BT

Fd. OK April 25, 1977 by L Monrean, DCSO - C.S. File 59/31-31
Fd. OK by C. Sweeden, July 1999 - M131-79

Fd. & used on BLM Dependent resurvey by Dale Bedell, Cadastral Surveyor, under Group #1728, surveyed May 1994-April 1995 - (DCSO records Vol. 52 Page(s) 19829)

The ¼ sec. cor. of secs. 13 and 14, perpetuated by Byron, in 1961, from original evidence no longer in evidence, as recorded in Douglas County Surveyor's Office; monumented with an iron post, 1¼" dia., firmly set, projecting 16" above ground, set in concrete, with brass cap (properly) mkd. from which bearing trees mkd. by Byron
A fir, 24" dia., bears N.60°E., 53 lks., with healed blaze
A fir, 17" dia., bears S.75°W., 92 lks., with healed blaze

Found OK by C. Sweeden, April 2003 - M142-8
Fd. Ok by C. Sweeden, 8/2005 - 2005-0084 A&B