

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 31 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 8 Page(s) 3297)

Marked a Fir tree, 30" dia. for 1/4 sec. cor. on South bdy. Sec. 31, from which
A Fir 24" dia., bears S.45°E., 5 lks. dist.
A Fir 48" dia., bears N.10°W., 24 lks. dist.

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3306 and 3307)

(24.00 chs.)
The old 1/4 sec. cor. which is a Fir 30" dia., mkd. 1/4 S on N. face, from which
A Fir 24" dia., bears S.45°E., 5 lks. dist. mkd. 1/4 S BT.
A Fir 48" dia., bears N.10°W., 24 lks. dist. mkd. 1/4 S BT.
(40.00 chs.) (West)
Set a post 3 1/2 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which
A Maple 6" dia., bears N.20°E., 37 lks. dist. mkd. 1/4 S BT
A Hemlock 7" dia., bears S.34°E., 29 lks. dist. mkd. 1/4 S BT.

GLO survey by Morris Wygant, compassman for Zachariah M. Derrick, U.S. Deputy Surveyor, under Contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 8 Page(s) 3386 and 3387)

(21.86 chs.)
Old 1/4 sec. cor. on S. bdy. Sec. 31 bears S. 10 lks., I destroy this corner.
(39.40 chs.) (West)
The 1/4 sec. cor. bet. secs. 6 and 31, which is a post mkd. and witnessed as described by the Surveyor General and which I now change to refer to Sec. 31, T24S R8W only.

BLM Resurvey by James E. Jelly; Harvey E. Wofford; Wayne L. Rogers, Cadastral Surveyors, under Group #'s 926 and 958 - Surveyed Aug. 1977/April 1979 - (DCSO records Vol. 42 Page(s) 16435)

Point for the 1/4 sec. cor. of sec. 31 only, determined by the method of irregular boundaries: there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
(Cont. Next Page)

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 31 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

T 24 S R 8 W
1/4 S 31
T 25 S R 8 W
1979

from which

A Hemlock 18" dia., bears N.38½°E., 75 lks. mkd. ¼ S31 BT.

A Hemlock 7" dia., bears N.83½°W., 36 lks. mkd. ¼ S31 BT.

Tony Hostetter - For: Weyerhaeuser Co. - Nov. 2013 - M167-6

Found - 1979 BLM cap as described vol. 42, pg. 16435.
18" hemlock stump, no marks bears; N.38½°E., 75 lks.
14" hemlock, BLM tag, bears; N.83½°W., 36 lks.
New BTs- 13" hemlock, scribed "S31 ¼ BT", BT TAG bears;
N.36°16'E., 32.4 feet to spike.
18" Cedar, scribed "S6 ¼ BT, BT tag bears;
S.18°20'W, 37.8 feet to spike.