

PRIMARY CORNER DESCRIPTION East 1/4 Cor. for Sec. 24 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3220)

Set a post 3½ ft. long, 3" sq., 24" in the ground for ¼ sec. cor., marked ¼ S on W. face, from which
A Fir 36" dia., bears S.78°E., 141 lks. dist. mkd. ¼ S BT
A Fir 18" dia., bears S.75°W., 92 lks. dist. mkd. ¼ S BT

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam, crew - Sept. 1, 1960 - C.S. 49/41-36

Found - Orig. 36" now 40" Fir snag S.78°E., 93.1 ft. shows good bark scribe "¼S".
Orig. 18" now down and mostly rotted Fir, I find parts of scribe marks and parts of old axed face, S.75°W., 60.7 ft.

Set Brass cap at cor. mkd: County Surveyors Office
E ¼ S24 | T 24 S R 8 W
1960

This corner renewed by Evans in 1956 (C.S. 42/198) and I find both of his BTs. The snag bears S.88°E., rec. S.78°E. This is not a common corner as renewed by Evans. From brass cap, Evan's corner bears S.7°W. 14.0 ft. I destroy scribing on Evan's BTs

New BTs- 24" R.Fir bears S.79°W., 46.8 ft. scribed ¼ S24 CSBT
14" W.Fir bears S.36°W., 9.5 ft. scribed ¼ S24 CS BT

Fd. OK Nov. 20, 1981 by Les Roberts - M 90-12

Ronald Rice - Roseburg Resources Co. - 6/2003 - M142-47

Found - 2½" County Surveyors brass cap dated 1960 with the following accessories:

26" W.Fir (Rec. R.Fir) bears S.79°W., 46.8' (healed face)

34" D.Fir (rec. W.Fir) bears S.36°W., 9.5' (healed face)

2½" brass cap marking the W¼ cor. of sec. 19 bears N.0°16'28"W., 43.06'

New BT - 8" D.Fir bears S.52½°E., 22.0' blazed, scribed "X BT" at base.

Note - Existing corners or corner established as a result of this survey have a galvanized steel post adjacent to the corner monument and accessories have red painted bands & BT tags where appropriate.

cont. next pg

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION East 1/4 Cor. for Sec. 24 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor and Robert H. Browning, Survey Tech, under special instructions and Group No. 2104, surveyed July 2005/Jan. 2006 (DCSO records Vol. 57 Page(s) 22390-1)

The ¼ sec. cor. of sec. 24 only, on the E. bdy. of the Tp., remonumented by the Douglas County Surveyors Office in 1960 from orig. evidence no longer in existence, and perpetuated by Rice, in 2003, monumented with an iron post, 1¼" dia., firmly set, projecting 11" above ground, with brass cap (properly) mkd.

from which BTs mkd. by the Douglas County Surveyors Office
A fir, 33" dia., bears S.33½°W., 9.5 ft., with a healed blaze.
A fir, 26" dia., bears S.80½°W., 46.2 ft., with a healed blaze.
and bearing tree mkd. by Rice
A fir, 8" dia., bears S.56½°E., 21.8 ft., with scribe marks X BT visible on a partially healed blaze.