

TOWNSHIP 24 RANGE 09 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION South 1/4 Cor. Sec. 32

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #292, dated Aug 7, 1878 - (DCSO records Vol. 8 Page(s) 3391)

-----  
Set fir post 40" long 5" dia., 18" in ground for the ¼ sec. cor. on S bdy of sec. 32, from which  
    A fir, 30" dia., bears N.25°E., 28 lks.  
    A fir, 36" dia., bears S.35°W., 5 lks.

Tony Hostetter - For: Weyerhaeuser Co. - Sept. 2015 - C.S. File 65/89-61

-----  
Found - 3/4 iron pipe, listed in Weyerhaeuser Co records as being set in 1959 based on the found original BT listed below. From which:  
    36" Fir stump, WEYCO tag, bears; S.76°W., 21.0 ft to center.  
Note - Weyerhaeuser bearings typically measured by staff compass.  
New BTs- 14" hemlock stump , BT tag, bears: N.11°E., 5.9 ft to 6" spike, placed below tag.  
    18" fir stump, BT tag, bears: N.21°E., 21.2 ft to 6" spike, placed below tag  
    18" fir stump, BT tag, bears: S.17°W., 4.1 ft to 6" spike, placed below tag  
    12" fir stump, BT tag, bears: N.57°W., 5.1 ft to 6" spike, placed below tag  
Note - New BT bearings determined by hand compass (decl 18°E)