

TOWNSHIP 24 RANGE 09 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 33 (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #292, dated Aug 7, 1878 - (DCSO records Vol. 8 Page(s) 3390)

-----  
Set laurel post, 3 ft. long, 5" dia., 18" in ground, for the 1/4 sec. corner on S. Bdy. of Sec. 33, from which a  
    Fir, 24" dia., bears S.38°W., 6 lks.  
    Fir, 16" dia., bears N.65°W., 24 lks.

-----  
Tony Hostetter - For: Weyerhaeuser Co. Co. - March 2009 - C.S. File 65/69-10

-----  
Found - 3/4" iron pipe (1971 Weyerhaeuser records indicate that 2 orig. GLO BTs were fd., A 3/4" iron pipe was set at that time, from which  
    18" fir stump, OBT, scribing visible, Weyco tag & "W" nail, bears N.27°E., 5.3 ft. to center. (GLO 18" Fir, N.27°E., 8 lks.)  
    24" fir stump, OBT, scribing visible, Weyco tag & "W" nail, bears S.40°W., 2.6 ft. to center. (GLO 16" Fir, N.40°W., 4 lks.)  
    24" fir stump, Weyco tag & "W" nail, bears N.49½°E., 12.5 ft. to "W" nail.  
New BTs- 15" fir, Weyco tag & spike, bears N.35°E., 18.2 ft. to spike.  
          14" fir, Weyco tag & spike, bears S.12°E., 23.3 ft. to spike.  
          15" fir, Weyco tag & spike, bears S.52°W., 31.6 ft. to spike.

CORNER LOCATION (GARMIN 60 CSX GPS)  
43°25'54.1"N  
123°46'7.9"W