

TOWNSHIP 25 RANGE 01E POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 31 (S); only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Joseph A Ganong & John G Collins, US Cadastral Engineers under instructions dated March 12, 1921, surveyed May 1927/June 1928 - (DCSO Records Vol. 21 Page(s) 9143)  
-----  
Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor. of sec. 31 only, with brass cap marked  
1/4 S 31  
1927  
from which  
    A fir, 8" dia., bears N.25°E., 96 lks., mkd: 1/4 S31 BT.  
    A fir, 6" dia., bears N.75°W., 21 lks., mkd: 1/4 S31 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage & D. West - March/April 1967 - C.S. File 52/30-74  
-----  
Found - 1927 US GLO Brass Cap properly marked & BTs as follows:  
    8", now 9" Fir Stump, N.25°E. 63.1. ft., shows "BT" scribe on unhealed blaze.  
    6", now 9" Fir, Alive, N.75°W. 13.9 ft., shows good scar. Don't open,  
New BT - 7" D.Fir N.58°E. 16.9 ft. mkd. 1/4 S31 CS BT.  
Note - This corner lies 100 ft. N. of Canton Creek Access Road.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 5/2024 - C.S. File 67/58-24  
-----  
No renewal done but:  
Oregon Coordinate Reference System  
Cottage Grove - Canyonville Zone  
N 104802.621           E206523.465  
(Outside of the Archie Creek burn area.)