

TOWNSHIP 25 RANGE 01E POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Cor. Secs. 25, 36; 30 & 31 T25-2E

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Joseph A Ganong & John G Collins, US Cadastral Engineers under instructions dated March 12, 1921, surveyed May 1927/June 1928 - (DCSO Records Vol. 21 Page(s) 9145)

-----  
Set an iron post, 3 ft. long, 2" dia., 27" in the ground, for cor. of secs. 25, 30, 31, & 36, with brass cap mkd

T25S  
R1E|R2E  
S 25|S 30  
S 36|S 31  
1927

from which

- A fir, 15" dia., bears N.32°E., 62 lks., mkd: T25S R2E S30 BT.
- A cedar, 10" dia., bears S.42°E., 46 lks., mkd: T25S R2E S31 BT.
- A fir, 12" dia., bears S.56°W., 34 lks., mkd: T25S R1E S36 BT.
- A fir, 10" dia., bears N.86°W., 32 lks., mkd: T25S R1E S25 BT.

Jim Landrum, USFS & Deputy, Doug. Co. Surveyors Office -  
Witness: Leonard Herzstein - May 12, 1983 - C.S. 62/10-3

- 
- Found - 1927 GLO brass cap, properly mkd., on 2" iron post, firmly set, projecting 6" above the ground.
- A 20" D.Fir, N.32°E., 40.9 ft. with healed blaze.
  - A 21" R.Cedar, S.42°E., 29.6 ft. (Rec. 30.4 ft.) with healed blaze.
  - A 17" W.Fir, S.56°W., 21.5 ft. (Rec. 22.4 ft.) with healed blaze.
  - A roothole, N.86°W., 21.1 ft. with decayed log, size indeterminate, alongside with fragmentary scribe marks visible on decayed blaze.
- No new monument set.
- New BT - A 20" D.Fir, N.34°W., 23.1 ft. scribed "T25S R1E S25 CS BT" on a single blaze.
- Note - Corner is located on a steep NW slope, approx. 300 ft. east of the end of USFS Road #4760-400.