

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 104460

PRIMARY CORNER DESCRIPTION N 1/16 120 Sec 18

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM resurvey by A. Bert Skeesick & Daniel E. Weller, Cadastral Surveyors under Group #1888, surveyed Sept. 1998/Sept. 1999 - (DCS0 rec. Vol. 53 Page(s) 20707-8)  
-----  
Point for the N 120 1/16 sec. cor. of sec. 18, at its calculated position.  
Set a stainless steel post, 28" long, 2½" dia., 25" in the ground, with brass cap mkd. T 25 S R 1 W  
1/16  
N 120  
S 18  
1999  
from which  
A fir, 17" dia., bears N.47°E., 15 lks., mkd. N 120 1/16 S18 BT.  
A fir, 9" dia., bears N.85°W., 64 lks., mkd. N 120 1/16 S18 BT.  
Deposit a magnet in a white plastic case at the base of the stainless steel post.

Ron Rice - For: Seneca Jones Timber Co. & Roseburg Resources Co. - June 2009 - M159-39  
-----  
Symbol shown on map for 1/16 corner.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 4/20/2023 - C.S. File 67/56-9  
-----  
Found - 3¼" BLM brass cap (properly mkd)  
Sawn burned 22"x1.5 ft. Fir stump N.47°E., 9.4 ft.  
Add 2" PK nail top center.  
Burned dead 14" D.Fir N.85°W., 39.0 ft. (rec. 64 lks 42.2 ft.) add 3½" mag nail, right side center, fully healed single blaze.  
New - 5/8"x30" iron rod with yellow DCS0 plastic cap S.24°E., 19.5 ft up 6"  
Note - Area burnt 9/2020  
Compass decl. 14½°E.  
Lat: 43°24'15.98"N Long: 122°52'12.66"W