

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 30 & 31

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3555)</p> <p>-----</p> <p>The point for ¼ sec. cor., falls on bare bed rock, facing NW &amp; at the exact cor. point, I cut a cross (+) for ¼ sec. cor., &amp; mark ¼ on N side of cross, from which</p> <p style="padding-left: 40px;">A fir, 7" dia., bears S.14°W., 31 lks., mkd: ¼ S31 BT.</p> <p style="padding-left: 40px;">A fir, 6" dia., bears N.86°W., 79 lks., mkd: ¼ S30 BT.</p>
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Clete Putnam - Oct. 1962 - C.S. File 52/30-2</p> <p>-----</p> <p>Found - "X" &amp; "¼" in bedrock according to Gov't field notes. Rotted remnants of Fir Stump S.14°W. 20.5 ft. Rotted remnants of Fir tree N.86°W. 52.1 ft., no scribing fd.</p> <p>New - Impossible to Set Brass Cap in this location, solid bed rock.</p> <p>New BTs- 16" D.Fir N.62°E., 78.3 ft.(slope meas.) Mkd: ¼ S30 CS BT</p> <p style="padding-left: 40px;">10" D.Fir S.55°E., 72.6 ft. (level meas.) Mkd: ¼ S31 Cs BT.</p>
<p>Fd. Ok Oct. 1966, DCSO C.S. File 52/30-41A</p>
<p>BLM Dependent resurvey by James E. Jelley, Cadastral Surveyor under Group #350 &amp; 929 surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16349)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 30 &amp; 31, perpetuated &amp; recorded by Godfrey, in 1961, mkd. with an X in NW. face of rock outcropping, from which the remains of the original BTs:</p> <p style="padding-left: 40px;">A root hole, bears N.86°W., 79 lks.</p> <p style="padding-left: 40px;">A root hole, bears S.14°W., 31 lks.</p> <p>and bearing trees mkd. by Godfrey</p> <p style="padding-left: 40px;">A fir, 16" dia. bears N.62°E., 105 lks. with healed blaze.</p> <p style="padding-left: 40px;">A fir, 10" dia., bears S.55°E., 110 lks. with healed blaze</p> <p>At the corner point</p> <p>Set a brass tablet, 3¼" dia., 3½" stem, in drill hole, in rock outcropping, with top mkd.</p> <div style="text-align: center;"> <p>T25S R1W</p> <p>¼     <u>S 30</u></p> <p>          S 31</p> <p>1978</p> </div>
<p>Fd. OK by BLM 3/17/1992 - C.S. File 63/140-5</p>
<p>continued next page</p>

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 30 & 31

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

Fd. BC & 2 BTs by John Ransom, 6/2011 - M162-51