

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3553)

-----  
Set a basalt stone, 16x8x8", 11" in the ground for cor. of secs. 29, 30, 31, & 32, marked with 1 notch on S & 5 notches on E edges, from which

A fir, 14" dia. bears N.81°E. 53 lks. mkd: T25S R1W S29 BT  
A fir, 16" dia., bears S.89½°E., 49 lks., mkd: T25S R1W S32 BT.

No other tree in limits, raised a mound of stone, 2 ft. base, 1½ ft. high, West of corner.

Pits impracticable.

BLM Dependent resurvey by James E. Jelley, Cadastral Surveyor under Group #350 & 929 surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16347)

-----  
Point for the cor. of secs. 29, 30, 31, & 32, proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2½" dia., 24" in the ground, with brass cap marked:

T25S R1W  
S 30 | S 29  
S 31 | S 32  
1978

from which

A fir, 9" dia., bears N.67¼°E., 37½ lks., mkd: T25S R1W S29 BT.  
A fir, 15" dia., bears S.15½°E., 77 lks., mkd: T25S R1W S32 BT.  
A fir, 11" dia., bears S.48°W., 101 lks., mkd: T25S R1W S31 BT.  
A fir, 10" dia. bears N.15°W., 20 lks mkd: T25S R1W S30 BT

Fd. Ok by BLM 3/17/1992 - C.S. File 63/140-3

John Ransom, USFS - Jonathan Drew - 1/17/2011 - C.S. File 65/72-12 & M162-51 (June 2011)

-----  
Found - (Monument) None Found, recent fire activity and where corner should fall is newly created vehicle turn out created by CAT. No trace of existing monument found in fill.

19" Fir Snag S.47°57'W., 66.24 ft healed double blaze.

21" Fir Snag S.14°41'E., 50.89 ft. healed double blaze.

20" Fir N.16°40'W., 12.95 ft healed double blaze

continued next page

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Set - 15" Fir N.67°23'E., 24.19 ft healed double blaze.  
3" Brass Cap on 2½" Galvanized Iron Pipe from existing evidence. Marked "US DEPT OF AGRICULTURE FOREST SERVICE" "T25S R1W S30 S29 S31 S32 LS2561 2010" "CADASTRAL SURVEY - UNLAWFUL TO DISTURB" Set projecting 3" above mound of stone painted mound red.

Painted BTs red with 6" wide band at head height, painted face blaze, new nails on tags. Added 2 New Trees:

21" Fir Bears S.58°54'W., 79.17 ft. Scribed "T25SR1WS31"BT" on double blaze.

21" Fir Bears S.49°58'E., 13.39 ft. Scribed "T25SR1WS32"BT" on double blaze

All new trees include a 3/4" brass washer nailed between B and T on lower blaze, Washer stamped "LS2561"

Note - To get to this corner from CR 78 take BLM 16 Road East towards Mace Mt. Continue on Forest Road 500 past Mace Mt lookout turnoff corner on left Corner falls in middle of new vehicle turn out, ring of red painted stones.

PLANE COORDINATE POSITION DATA

State: OR Zone: UTM-10M

North: 4801245

East: 512975

Estab. By: GCDB