

PRIMARY CORNER DESCRIPTION Cor Secs 28, 29, 32, & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3541-2)

Set a basalt stone, 20x10x9", 15" in the ground for cor. of secs. 28, 29, 32, & 33, marked with 1 notch on S & 4 notches on E edges, from which

A fir, 5" dia. bears N.46°E., 15 lks. mkd: T25S R1W S28 BT
A fir, 26" dia. bears S.40°E. 23 lks. mkd: T25S R1W S33 BT
A chinq 8" dia. bears S.49½°W. 40 lks mkd: T25S R1W S32 BT
A dogwood, 6" dia., bears N.35°W., 40 lks., mkd: T25S R1W S29 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Clete Putnam - Oct. 1961 - C.S. File 52/30-3

Found - Rock as called for in Gov't notes lying on ground near corner.

Rotten Fir snag, 30" S.40°E. 15.2 ft good scribing vis
Clump of young Chinquapins S.49½°W., 26.4 ft.
Clump of young Dogwoods N.35°W., 26.4 ft.
No trace found of NW BT

Set - Brass cap mkd: County Surveyors T25S R1W S 29|S 28
Office 1961 S 32|S 33

Set orig. rock alongside.

New BTs- 8" D.Fir N.30°W., 4.9 ft. mkd: T25S R1W S29 CS BT.
10" D.Fir N.44°E., 26.3 ft. mkd: T25S R1W S28 CS BT.
7" D.Fir S.39°E., 7.6 ft. mkd: T25S R1W S33 CS BT.
5" D.Fir S.31°W., 14.6 ft. mkd: S32 CS BT.

Fd. & used on BLM Dependent resurvey by James E. Jelley, Cadastral Surveyor under Group #350 & 929 surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16341)

BLM Dependent resurvey by James E. Jelley, Cadastral Surveyor under Group #350 & 929 surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16348)

Point for the ¼ sec. cor. of secs. 29 & 32, at proportionate dist; there is no remaining evidence of the original corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd.

T25S	R1W
¼	<u>S 29</u>
	<u>S 32</u>

1978

from which

A fir, 10" dia., bears N.43°W., 30½ lks., mkd. ¼ S29 BT.
A fir, 14" dia., bears S.14½° E., 9 lks., mkd. ¼ S32 BT

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Cor Secs 28, 29, 32, & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. ok 3/17/1992 BLM C.S. File 63/140-4

Russell Badgley - For: Seneca Jones Timber Co. - 1/2021 - M178-23

Found - A 1" iron post by Godfrey with the DCSO IN 1961, firmly set and projecting 13" above the ground, with a 2½" brass cap (properly) mkd, from which BTs by DCSO in 1961 -

A 19" D.Fir, burned by fire & now a 4 ft. high stump with a 6" nail in the top, bears N.41°00'W., 4.3 ft w/healed blaze (N.30°W., 4.9')

A 25" D.Fir, burned by fire & now a 4 ft. high stump with a 6" nail in the top, bears N.45°30'E , 25.6 ft w/healed blaze (N.44°E., 26.3')

A 17" D.Fir, burned by fire & now a 4 ft. high stump with a 6" nail in the top, bears S.34°45'E., 7.7 ft w/healed blaze (S.39°E., 7.6')

A 10" D.Fir, burned by fire & now a 4 ft. high stump with a 6" nail in the top, bears S.31°30'W., 14.4 ft w/healed blaze (S.31°W., 14.6')

New RMs- A 5/8"x30" iron rod with 2" alum. cap mkd. "RM1 2020 PLS70716" bears S.80°53'00"W. 12 71 ft

A 5/8"x30" iron rod with 2" alum. cap mkd. "RM2 2020 PLS70716" bears N.7°30'26"E 24.30 ft

NAD83 (2011):

Latitude: 43°21'51.15671"N Longitude: 122°49'13.85249"W