

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 28

Alias	Description

GLO survey by Hezekian H. Johnson, Deputy Surveyor, under Contract #721, dated May 1, 1900 (DCSO rec. Vol. 9 Page 3546)

Set a basalt stone, 16x8x6", 11" in the ground for 1/4 sec. cor. marked 1/4 on N face, from which
 A Cedar, 10" dia., bears S.74°E., 55 lks., mkd: 1/4 S28 BT.
 A Fir, 20" dia., bears N.33°W., 21 lks., mkd: 1/4 S21 BT.

Reported as not found by Vernon "Ray" Tracy, May 1967 - C.S. File 52/30-79A

BLM resurvey by A. Bert Skeesick & Daniel E. Weller, Cadastral Surveyors under Group #1888, surveyed Sept. 1998/Sept. 1999 - (DCSO rec. Vol. 53 Page(s) 20688-9)

Point for the 1/4 sec. cor. of secs. 21 & 28, at proportionate dist.; there is no remaining evidence of the original corner. Set a stainless steel post, 28" long, 2 1/2" diam., 22" in the ground, in a collar of stone, with brass cap mkd.
 T 25 S R 1 W
 1/4 S 21
 S 28
 1999
from which
 A fir, 7" diam., bears S. 64° E., 22 lks., mkd. 1/4 S28 BT.
 A fir, 7" diam., bears N. 3° W., 45 lks., mkd. 1/4 S21 BT.
Deposit a magnet in a white plastic case at the base of the stainless steel post.

Russell Badgley - For: Seneca Jones Tmbr Co - 1/2021 - M178-23

Found - A 2 1/2" iron post by the BLM in 1999, firmly set and projecting 6" above the ground, with a 3 1/4" brass cap (properly) marked, from which
 BTs by the BLM in 1999 -
 A 8" D.Fir bears N.4°30'W., 29.9 ft with healed blaze (N.3°W., 45 lks) 2002 BLM
New RMs- A 5/8"x30" iron rod with 2" alum. cap mkd. "RM1 PLS70716" bears N.59°46'25"E. 16.64 ft.
 A 5/8"x30" iron rod with 2" alum. cap mkd. "RM2 PLS70716" bears S.30°07'50"E 17.44 ft
NAD83 (2011):
Latitude: 43°22'43.94585"N Longitude: 122°48'38.53085"W