

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11

Alias	Description

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3527)

Set a cedar post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor., mkd: 1/4 S10 on W, S11 on E faces, from which
A cedar, 8" dia., bears N.72°W., 28 lks., mkd: 1/4 S10 BT.
A hemlock, 18" dia., bears S.70°E., 25 lks., mkd: 1/4 S11 BT

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Clete Putnam - June 6, 1962 - C.S. 52/30-10

Found - 3/4" iron reinforcing rod in mound of rock at corner. Cedar N.72°W., 18.5 ft., down & badly rotted, faint portions of scribe marks barely visible on badly rotted faces (2 faces).
Rotted remnants of Hemlock stump S.70°E., 16.5 ft., too far gone to find any marks.

New BTs- 14" Hemlock S.64°W., 20.1 ft. MKD: 1/4 S10 CS BT.
11" D.Fir N.23°E., 31.0 ft. MKD: 1/4 S11 CS BT.
Corner lies approx. 200 ft. West of Canton Creek.

Fd. Ok by T. Shrum, 12/1966 - M32-63

Adam DeGroot - For: Seneca Jones Timber Co. - July 2020 - M177-19

Found - A 3/4" Iron rod reported by DCSO in 1962 per CS 52/30, firmly set in a 24" diam. by 12" high mound of stone, and projecting 6" above the mound.
from which BTs by DCSO in 1962 -
A 26" Hemlock bears S.62°15'W., 20 2 ft w/healed dbl blaze and "X" (S.64°W., 20 1 ft)

And BTs by others -
A 20" Hemlock bears N.53°E., 34.3 ft w/healed dbl blaze and "X"

New BTs- A 9" Hemlock bears S.45°45'E., 39.1 ft scribed "1/4 S11 BT" on dbl blaze.
A 7" Hemlock bears N.2°15'W., 18.1 ft scribed "1/4 S10 BT on dbl blaze.

Lat: 43°24'53.87344"N Long: 122°46'56.25921"W