

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3608)</p> <p>-----</p> <p>Set a basalt stone 22x10x6", 16" in the ground for ¼ sec. cor. mkd ¼ on W face, from which</p> <p> A cedar, 16" dia., bears N.40°E., 24 lks., mkd: ¼ S23 BT.</p> <p> A hemlock, 7" dia., bears S.55°W., 12 lks., mkd: ¼ S22 BT.</p>
<p>Douglas Co. Surveyors Office - James Byron, Deputy - M. Godfrey & S. Bilow - July 14, 1958 - C.S. File 49/102-4</p> <p>-----</p> <p>Found - Rock Mkd. "¼" on W. Side.</p> <p> Hemlock, now 16" diam. S.55°W. 7.9 ft. ("¼ S2" now visible)</p> <p>Set Brass Cap at Cor Mkd: S22/S23 T25S R2W County Surveyor's Office, 1958</p> <p>New BTs- 60" Fir stump S.77°E. 39 ft. scribed "¼ S23 CS BT"</p> <p> 11" Hemlock S.86½°W. 40 ft. scribed "¼ S22 CS BT".</p>
<p>Glen McChesney, Wey Co. - 8/1/1958 - C.S. File 53/112-29</p> <p>-----</p> <p>Found - DCSO brass cap</p> <p> 14" Hemlock, S.65°W., 7.9 ft., scribing visible.</p> <p> 52" Fir stump, S.77°E., 36.5 ft., scribed "CS BT"</p> <p> 10" Hemlock, S.85°W., 39.3 ft., scribed "CS BT"</p> <p>New - Added "W" nail & Plate to 52" Fir stump.</p> <p> 52" Fir, N.50°W., 19.5 ft., "W" nail & plate.</p>
<p>BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1979, surveyed May 2001/June 2002- (DCSO rec. Vol. 54 Page(s) 20921-2)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 22 & 23, perpetuated by Byron, in 1958, monumented with an iron post, 1½" dia., firmly set, projecting 15" above ground, in a mound of earth, 2 ft. dia., 6" high, surrounded by a large truck tire, with brass cap (properly) mkd.</p> <p>from which the remains of an original bearing tree</p> <p> A roothole, bears N.34¼°E., 15.8 ft., with decayed cedar trunk lying alongside, no marks visible. (Record, N.40°E.)</p> <p>and remains of bearing trees mkd. by Byron</p> <p> A fir stump, 60" dia., bears S.78½°E., 39.2 ft., with scribe marks S23 CS BT visible on unhealed blaze.</p> <p> A decayed hemlock stump, 16" dia., bears S.83¾°W., 39.5 ft., with illegible scribe marks visible on partially healed double blaze.</p> <p>continued next page</p>

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

and a bearing tree mkd. by person(s) unknown
A fir, 52" dia., bears N.50°W., 21.2 ft., with letters MC
and axe marks visible in the bark.
and new bearing trees
A hemlock, 12" dia. bears N.14¼°E., 19.5 ft. mkd. ¼ S23 BT
A fir, 8" dia., bears S.70°W., 29.1 ft., mkd. ¼ S22 BT.

Mark Smalley, Roseburg Forest Products - Party Chief: William
Olson - Witness: Niel Danko - 9/2009 - C.S. File 65/66-44

Found - 1958 DCS0 cap, properly mkd.
51" D.Fir, N.50°W., 21.2', with letters MC visible
in the bark, and axe marks 1958 (Rec 52" dia)
13" Hemlock N.14¼°E. 19.5' partially healed face 2002
10" D.Fir, S.70°W., 29.1' partially healed face 2002
60" Fir stump, S.78½°E., 39.2', 1958, rotten.
16" Decayed hemlock stump, S.83¾°W., 39.5', 1958,
gone.
A roothole, N.34¾°E., 15.8', 1900. Roothole not well
defined.
14" Hemlock, S.65°W., 7.9', (Previous rec. as
S.55°W., 7.9'), 1958, gone.

New - 12" D.Fir, S.22°E., 11.4' measured to a nail in the
side-center of stump scribed "S23BT" with LS 2354
brass washer.
Compass decl. 18°E.